



APPENDIX N - STRUCTURAL SIGNIFICANT ITEMS CROSS REFERENCE

A. STRUCTURAL SIGNIFICANT ITEM CROSS REFERENCE

This is a cross reference for Structural Significant Items, Supplemental Structural Inspections and Fatigue Inspections.



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item Cross Reference Table

Structural Significant Items Cross Reference

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
27-41-I01	Horizontal Stabilizer Trim Actuator Safety Rod	27-41-I01	Safety Rod, Horizontal Stabilizer Trim Actuator	Zone 310, Section 48	1	27-701-01	27-701-01	27-701-01	January 2025	January 2025	-
27-41-I01	Horizontal Stabilizer Trim Actuator Safety Rod	27-41-I01	Safety Rod, Horizontal Stabilizer Trim Actuator	Zone 310, Section 48	1	-	-	-	-	-	September 2028
28-00-I01	Auxiliary Body Fuel Tanks	28-00-I01A	Auxiliary Body Fuel Tanks Internal Corner Angles	Outer Angle around periphery of Forward Panel & Lower Side Panel Edges	1	-	-	-	-	January 2025	-
28-00-I01	Auxiliary Body Fuel Tanks	28-00-I01B	Auxiliary Body Fuel Tank Inner Skin	At Fastener Holes of Panels Connecting to Diaphragms	1	-	-	-	-	January 2025	-
52-10-I02	Passenger Entry Doors - Skin and Door Structure	52-10-I02	Passenger Doors Outer Skin and Structure	Outer Skin Between Handle and Window Cutouts	2	52-701-01	52-701-01	52-701-01	May 2028	May 2028	September 2035
						52-701-03	52-701-03	52-701-03	May 2028	May 2028	September 2035
52-34-I03	Fwd Large Cargo Door - Latch Cam Support & Shear Tie Fittings	52-34-I03A	Large Cargo Door Latch Support Frame Fittings	Latch Cam Support Fitting Lug Bore	2	52-702-01	52-702-01	52-702-01	May 2028	May 2028	September 2035
52-34-I03	Fwd Large Cargo Door - Latch Cam Support & Shear Tie Fittings	52-34-I03B	Large Cargo Door Latch Support Frame Fitting (135W1191)	Outer Chord	2	52-703-01	52-703-01	52-703-01	May 2028	May 2028	September 2035
52-34-I05	Fwd Large Cargo Door - Skin and Door Structure	52-34-I05A	Large Cargo Door Latch Frame Inner Chord	Splice to Latch Support Fitting	1	52-704-01	52-704-01	52-704-01	January 2025	January 2025	September 2028



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
52-34-I05	Fwd Large Cargo Door - Skin and Door Structure	52-34-I05B	Large Cargo Door Outer Skin at Attachment to Main Hinges	Outer Skin and Latch Frame Outer Chord	1	52-705-01	52-705-01	52-705-01	January 2025	January 2025	September 2028
52-37-I03	Aft Large Cargo Door - Latch Cam Support & Shear Tie Fittings	52-37-I03A	Large Cargo Door Latch Support Frame Fittings	Latch Cam Support Fitting Lug Bore	2	52-706-01	52-706-01	52-706-01	May 2028	May 2028	September 2035
52-37-I03	Aft Large Cargo Door - Latch Cam Support & Shear Tie Fittings	52-37-I03B	Large Cargo Door Latch Support Frame Fitting (135W1191)	Outer Chord	2	52-707-01	52-707-01	52-707-01	May 2028	May 2028	September 2035
52-37-I05	Aft Large Cargo Door - Skin and Door Structure	52-37-I05A	Large Cargo Door Latch Frame Inner Chord	Splice to Latch Support Fitting	1	52-708-01	52-708-01	52-708-01	January 2025	January 2025	September 2028
52-37-I05	Aft Large Cargo Door - Skin and Door Structure	52-37-I05B	Large Cargo Door Outer Skin at Attachment to Main Hinges	Outer Skin and Latch Frame Outer Chord	1	52-709-01	52-709-01	52-709-01	January 2025	January 2025	September 2028
52-38-I01	Main Deck Cargo Door - Main Latch Cam Assemblies	52-38-I01	Main Deck Cargo Door - Main Latch Cam Assemblies	Main Rotary Cam Latch - Cam Shaft	1	-	-	-	-	-	September 2028
52-38-I03	Main Deck Cargo Door - Latch Cam Support & Shear Tie Fittings	52-38-I03A	Main Deck Cargo Door - Latch Cam and Roller Support Fittings	Latch Cam Support Fitting Lug Bore	2	-	-	-	-	-	September 2035
52-38-I03	Main Deck Cargo Door - Latch Cam Support & Shear Tie Fittings	52-38-I03B	Main Deck Cargo Door - Latch Cam and Roller Support Fittings	Latch Cam Support Fitting - Outer Chord	2	-	-	-	-	-	September 2035
52-38-I05	Main Deck Cargo Door - Skin and Door Structure	52-38-I05A	Main Deck Cargo Door - Latch Cam and Roller Support Fittings	Latch Cam Support Fitting - Latch Frame Inner Chord Splice to Latch Support Fitting	1	-	-	-	-	-	September 2028



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
52-38-I05	Main Deck Cargo Door - Skin and Door Structure	52-38-I05B	Main Deck Cargo Door - Skin and Door Structure	Outer Skin at Attachment to Main Hinges: Outer Skin and Latch Frame Outer Chord.	1	-	-	-	-	-	September 2028
53-00-I01	-	53-00-I01	Upper Lobe Skin Panels	Entire Fuselage - Skin BS 132.5 to BS 2150 Above WL 200 Except Under Fairings	2	53-701-01	53-701-01	53-701-01	May 2028	May 2028	-
53-00-I02	-	53-00-I02	Lower Lobe Skin Panels	Entire Fuselage - Skin BS 132.5 to BS 2150 Below WL 200 Except Under Fairings	2	53-702-01	53-702-01	53-702-01	May 2028	May 2028	-
53-00-I03	-	53-00-I03	Upper and Lower Lobe Skin Panels	Sections 43, 46, 47 - Skin Under Fairings	2	53-703-01	53-703-01	53-703-01	May 2028	May 2028	-
53-10-I02	Crown Skin Panel - BS 246 - 655	53-10-I02A	Crown Skin Antenna Installation - TCAS	Body Station 455.5 @ B.L. 0	2	53-704-01	53-704-01	53-704-01	May 2028	May 2028	September 2035
53-10-I02	Crown Skin Panel - BS 246 - 655	53-10-I02B	ACL Installation External Doubler	Crown Skin STA 602, BL 0 Under Stringer	2	53-705-01	53-705-01	53-705-01	May 2028	-	-
53-10-I02	Crown Skin Panel - BS 246 - 655	53-10-I02C	ACL Installation External Doubler	Crown Skin STA 602, BL 0 at Cutout	2	53-706-01	53-706-01	53-706-01	May 2028	-	-
53-10-I02	Crown Skin Panel - BS 246 - 655	53-10-I02D	Crown Skin Production ACL Installation	Crown Skin STA 602.5, BL 0	2	53-707-01	53-707-01	53-707-01	May 2028	May 2028	September 2035
53-10-I06	Lower Lobe Skin Panels - BS 246 - 655	53-10-I06	Ground Maneuver Camera Installation	Lower Lobe STA 604.06 @ BL 0	2	-	-	53-708-01	May 2028	-	-
53-10-I07	Longitudinal Skin Lap Splices	53-10-I07A	Longitudinal Skin Lap Splices Inner Skin	Typical - All Section 41 Lap Splices	2	53-709-01	53-709-01	53-709-01	May 2028	May 2028	September 2035



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
53-10-I07	Longitudinal Skin Lap Splices	53-10-I07B	Longitudinal Skin Lap Splices Outer Skin	Typical - All Section 41 Lap Splices	2	53-710-01	53-710-01	53-710-01	May 2028	May 2028	September 2035
53-10-I09	Entry Door - Cutout Structure	53-10-I09A	Passenger Entry Door #1 - Cutout	Upper Corner @ STA 332.5 and Lower Corner @ STA 382	2	53-711-01	53-711-01	53-711-01	May 2028	May 2028	September 2035
53-10-I09	Entry Door - Cutout Structure	53-10-I09B	Passenger Entry Door #1 - Cutout	Edge Frames @ STA 332.5 and STA 382	2	53-712-01	53-712-01	53-712-01	May 2028	May 2028	September 2035
53-10-I09	Entry Door - Cutout Structure	53-10-I09C	Passenger Entry Door #1 - Cutout	Bear Strap	2	53-713-01	53-713-01	53-713-01	May 2028	May 2028	September 2035
53-10-I09	Entry Door - Cutout Structure	53-10-I09D	Passenger Entry Door #1 - Cutout Upper Sill	Sta 309.5 to Sta 357.25	2	53-714-01	53-714-01	53-714-01	May 2028	May 2028	September 2035
53-10-I11	Large Cargo Door - Cutout Structure	53-10-I11A	Forward Large Cargo Door - Cutout	Upper Corner @ STA 501	2	53-715-01	53-715-01	53-715-01	May 2028	May 2028	September 2035
53-10-I11	Large Cargo Door - Cutout Structure	53-10-I11B	FWD Large Cargo Door - Cutout Outer Chord - Upper Sill	Body Station 592 to 613	1	53-716-01	53-716-01	53-716-01	January 2025	January 2025	September 2028
53-10-I11	Large Cargo Door - Cutout Structure	53-10-I11C	Forward Large Cargo Door - Cutout	Upper Sill, STA 487 to STA 508	2	53-717-01	53-717-01	53-717-01	May 2028	May 2028	September 2035
53-10-I11	Large Cargo Door - Cutout Structure	53-10-I11D	Forward Large Cargo Door - Cutout	Lower Sill, STA 592 to STA 634	2	53-718-01	53-718-01	53-718-01	May 2028	May 2028	September 2035
53-10-I14	Forward Access Hatch - Cutout Structure	53-10-I14	Forward Equipment Bay Access Hatch Cutout Structure	STA 143.5 to 172.5 Forward of NLG Well	2	53-719-01	53-719-01	53-719-01	May 2028	May 2028	September 2035
53-10-I16	E/E Access Hatch - Cutout Structure	53-10-I16	E/E Bay Access Hatch Cutout Structure	STA 360 to 382 Aft of NLG Well	2	53-720-01	53-720-01	53-720-01	May 2028	May 2028	September 2035
53-10-I18	No. 1 Crew Window Cutout	53-10-I18	NO. 1 Crew Window Cutout Structure	Lower Window Sill, Left and Right	2	53-721-01	53-721-01	53-721-01	May 2028	May 2028	September 2035
53-10-I20	No. 3 Crew Window Cutout	53-10-I20	NO. 3 Crew Window Cutout Structure	EF Window Post Between Windows 2 & 3, Left & Right	2	53-722-01	53-722-01	53-722-01	May 2028	May 2028	September 2035



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
53-10-I24	Nose Gear Wheel Well Top Panel	53-10-I24	NLG Well Top Panel	STA 246.2 Step Beam at BL 0	1	53-723-01	53-723-01	53-723-01	January 2025	January 2025	September 2028
53-10-I25	Nose Gear Wheel Well - Aft Bulkhead, BS 332.5	53-10-I25	WL 152 Beam (C/L 1 to 40)	Nose Wheel Well Aft Bulkhead @ STA 332.5 LBL and RBL 30	1	53-724-01	-	-	-	-	-
53-10-I25	Nose Gear Wheel Well - Aft Bulkhead, BS 332.5	53-10-I25	WL 152 Beam (C/L 41 and on)	Nose Wheel Well Aft Bulkhead @ STA 332.5 LBL and RBL 30	1	53-724-02	53-724-02	53-724-02	January 2025	January 2025	September 2028
53-10-I26	Nose Gear Wheel Well - Cutout Structure	53-10-I26-1	Nose Wheel Well Cutout Structure (C/L 1 to 40)	Forward End of Cutout LBL 30 to RBL 30	2	53-725-01	-	-	-	-	-
						53-725-07	-	-	-	-	-
53-10-I26	Nose Gear Wheel Well - Cutout Structure	53-10-I26-1	Nose Wheel Well Cutout Structure (C/L 41 and on)	Forward End of Cutout LBL 30 to RBL 30	2	53-725-02	53-725-02	53-725-02	May 2028	May 2028	September 2035
53-10-I26	Nose Gear Wheel Well - Cutout Structure	53-10-I26-2	Nose Landing Gear Well Cutout (C/L 1 to 40)	STA 332.5 Aft End of Cutout	2	53-725-03	-	-	-	-	-
						53-725-04	-	-	-	-	-
53-10-I26	Nose Gear Wheel Well - Cutout Structure	53-10-I26-2	Nose Landing Gear Well Cutout (C/L 41 and on)	STA 332.5 Aft End of Cutout	2	53-725-05	53-725-05	53-725-05	-	-	-
						53-725-06	53-725-06	53-725-06	-	-	-
53-10-I26	Nose Gear Wheel Well - Cutout Structure	53-10-I26-2	Nose Landing Gear Well Cutout	STA 332.5 Aft End of Cutout	2	-	-	-	May 2028	May 2028	September 2035
53-10-I29	Nose Landing Gear Trunnion Support Fitting	53-10-I29-1	Nose Wheel Well Trunnion Support Fitting (C/L 1 to 40)	BS 320.5, WL 121 to WL 133, Left & Right Side Free Flange	2	53-726-01	-	-	-	-	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
53-10-I29	Nose Landing Gear Trunnion Support Fitting	53-10-I29-2	Nose Wheel Well Trunnion Support Fitting (C/L 1 to 40)	BS 320.5, Left and Right Side, WL 181, Side Panel to Top Panel Joint	2	53-726-01	-	-	-	-	-
53-10-I29	Nose Landing Gear Trunnion Support Fitting	53-10-I29-1	Nose Wheel Well Trunnion Support Fitting (C/L 41 and on)	BS 320.5, WL 121 to WL 133, Left & Right Side Free Flange	2	53-726-02	53-726-02	53-726-02	May 2028	May 2028	September 2035
53-10-I29	Nose Landing Gear Trunnion Support Fitting	53-10-I29-2	Nose Wheel Well Trunnion Support Fitting (C/L 41 and on)	BS 320.5, Left and Right Side, WL 181, Side Panel to Top Panel Joint	2	53-726-02	53-726-02	53-726-02	May 2028	May 2028	September 2035
53-10-I30	Nose Landing Gear Drag Support Fitting	53-10-I30	NLG Drag Brace Fitting - Lug and Bushing Interface	STA 260, WL 173, RBL/LBL 30	1	53-727-01	53-727-01	53-727-01	January 2025	January 2025	September 2028
53-30-I01	Crown Skin Panel - BS 655 - 1035	53-30-I01A	Crown Panel Skin/Stringer Cracking Under Radome	S-3L to S-3R, BS 755.5 to 846	2	53-728-01	53-728-01	53-728-01	May 2028	May 2028	-
53-30-I01	Crown Skin Panel - BS 655 - 1035	53-30-I01B	Longitudinal Skin Crack Under Radome	BS 755.5 to 846, S-3L to S-3R	2	53-728-02	53-728-02	53-728-02	May 2028	May 2028	-
53-30-I01	Crown Skin Panel - BS 655 - 1035	53-30-I01C	Longitudinal Skin Crack Under Antenna Attach Angle or Skin Lug Fittings	BS 755.5 to 846, BTWN S-3L and S-3R	2	53-730-01	53-730-01	53-730-01	May 2028	May 2028	-
53-30-I03	Lower Lobe Skin Panel - BS 655 - 1035	53-30-I03	Fuselage Skin adjacent to Strakelet Attach Fitting (L/N 1-218)	STA 930 S-28 to S-30, STA 972 S-27 to S-29	2	53-731-01	53-731-01	53-731-01	-	-	-
53-30-I03	Lower Lobe Skin Panel - BS 655 - 1035	53-30-I03	Fuselage Skin adjacent to Strakelet Attach Fitting (L/N 219 and on)	STA 930 S-28 to S-30, STA 972 S-27 to S-29	2	53-731-02	53-731-02	53-731-02	May 2028	May 2028	September 2035



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
53-30-I05	Circumferential Skin/Stringer Splice BS 1035	53-30-I05-1	Fuselage Circumferential Skin/Stringer Splice, BS 1035 (L/N 75 - and on)	Bulkhead Outer Chord	1	53-733-01	53-733-01	-	-	January 2025	September 2028
53-30-I05	Circumferential Skin/Stringer Splice BS 1035	53-30-I05-1	Fuselage Circumferential Skin/Stringer Splice	BS 1035, Bulkhead Outer Chord	1	-	-	53-733-04	January 2025	-	-
53-30-I05	Circumferential Skin/Stringer Splice BS 1035	53-30-I05-2	Fuselage Circumferential Skin/Stringer Splice, BS 1035 (L/N 75 - and on)	Stringer End Fasteners	2	53-733-02	53-733-02	-	-	May 2028	September 2035
53-30-I05	Circumferential Skin/Stringer Splice BS 1035	53-30-I05-2	Fuselage Circumferential Skin/Stringer Splice	BS 1035, Stringer End Fasteners	2	-	-	53-733-05	May 2028	-	-
53-30-I05	Circumferential Skin/Stringer Splice BS 1035	53-30-I05-3	Fuselage Circumferential Skin/Stringer Splice, BS 1035 (L/N 75 - and on)	Paddle Fitting End Fasteners	2	53-733-03	53-733-03	-	-	May 2028	September 2035
53-30-I05	Circumferential Skin/Stringer Splice BS 1035	53-30-I05-3	Fuselage Circumferential Skin/Stringer Splice	BS 1035, Paddle Fitting End Fasteners	2	-	-	53-733-06	May 2028	-	-
53-30-I06	Longitudinal Skin Lap Splices	53-30-I06A	Longitudinal Skin Lap Splices Inner Skin (L/N 1-422)	Section 43 Lap Splices at S-14	2	53-734-01	53-734-01	53-734-01	-	-	-
53-30-I06	Longitudinal Skin Lap Splices	53-30-I06A	Longitudinal Skin Lap Splices Inner Skin (L/N 423 and on)	Section 43 Lap Splices at S-14	2	53-734-02	53-734-02	53-734-02	May 2028	May 2028	September 2035
53-30-I06	Longitudinal Skin Lap Splices	53-30-I06A	Longitudinal Skin Lap Splices Inner Skin	All Section 43 Lap Splices except S-14	2	53-734-03	53-734-03	53-734-03	May 2028	May 2028	September 2035



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
53-30-I06	Longitudinal Skin Lap Splices	53-30-I06B	Longitudinal Skin Lap Splices Outer Skin - Except Lower Row (S-45)	Typical - All Section 43 Lap Splices	2	53-735-01	53-735-01	53-735-01	May 2028	May 2028	September 2035
53-30-I08	Underwing Longerons	53-30-I08A	Underwing Longerons (L/N 1523, 1525 and on)	Underwing Longerons at Front Spar	FLS1	-	-	-	May 2028	May 2028	May 2028
53-30-I08	Underwing Longerons	53-30-I08B	Fuselage Skin at Underwing Longerons Doubler (L/N 1523, 1525 and on)	STA 972 to STA 1035, Stringer S-34 to S-38	FLS1	-	-	-	May 2028	May 2028	May 2028
53-30-I12	Entry Door - Cutout Structure	53-30-I12A	Passenger Entry Door #2 - Cutout	Upper Corner @ STA 739 and Lower Corner @ STA 788.5	2	53-736-01	53-736-01	53-736-01	May 2028	May 2028	-
53-30-I12	Entry Door - Cutout Structure	53-30-I12C	Passenger Entry Door #2 - Cutout	Bear strap	2	53-736-01	53-736-01	53-736-01	May 2028	May 2028	-
53-30-I12	Entry Door - Cutout Structure	53-30-I12B	Passenger Entry Door #2 - Cutout	Edge Frames @ STA 739 and STA 788.5	2	53-737-01	53-737-01	53-737-01	May 2028	May 2028	-
53-30-I12	Entry Door - Cutout Structure	53-30-I12D	Passenger Entry Door #2 - Cutout Upper Sill	Upper Sill, STA 718 to STA 755.5	2	53-739-01	53-739-01	53-739-01	May 2028	May 2028	-
53-30-I12	Entry Door - Cutout Structure	53-30-I12E	Passenger Entry Door #2 - Cutout	Lower Main Sill, STA 772 to STA 804	2	53-740-01	53-740-01	53-740-01	May 2028	May 2028	-
53-30-I13	Entry Door - Cutout Stop Fitting & Intercostals	53-30-I13	Passenger Entry Door #2 - Cutout Door Stop Backup Fitting	Fittings #7A & 8A, #1A & #2A, STA 788.5	2	53-741-01	53-741-01	53-741-01	May 2028	May 2028	-
53-40-I01	Crown Skin Panel - BS 1035 - 1434	53-40-I01	Satcom Antenna - Circumferential Cracking with Broken Stringer	STA 1077 to STA 1119 at Stringer 10 to 12	1	53-742-01	53-742-01	-	-	-	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
53-40-I01	Crown Skin Panel - BS 1035 - 1434	53-40-I01	Skin and Stringer at SATCOM antenna installation	STA 1077 to STA 1119 at Stringer 10 to 12	2	-	-	53-742-02	-	-	-
53-40-I01	Crown Skin Panel - BS 1035 - 1434	53-40-I01	Crown Panel, Skin and Stringer Section 44	At Skin to Stringer Fastener Locations	2	-	-	-	-	-	September 2035
53-40-I03	Longitudinal Skin Lap Splices	53-40-I03A	Longitudinal Skin Lap Splices Inner Skin (L/N 1-450)	Section 44 Lap Splices at S-14	2	53-743-01	53-743-01	53-743-04	May 2028	-	-
53-40-I03	Longitudinal Skin Lap Splices	53-40-I03A	Longitudinal Skin Lap Splices Inner Skin (L/N 451 and on)	Section 44 Lap Splices at S-14	2	53-743-02	53-743-02	53-743-02	May 2028	May 2028	September 2035
53-40-I03	Longitudinal Skin Lap Splices	53-40-I03A	Longitudinal Skin Lap Splices Inner Skin	All Section 44 Lap Splices except at S-14	2	53-743-03	53-743-03	53-743-03	May 2028	May 2028	September 2035
53-40-I03	Longitudinal Skin Lap Splices	53-40-I03B	Longitudinal Skin Lap Splices Outer Skin	Typical - All Section 44 Lap Splices	2	53-744-01	53-744-01	53-744-01	May 2028	May 2028	September 2035
53-40-I05	Front Spar Bulkhead - BS 1035	53-40-I05	Front Spar Side Fitting Inner Chord Splice	BS 1035, Upper Crown Splice at Top Centerline and Stringer 21	2	53-745-01	53-745-01	53-745-01	May 2028	May 2028	September 2035
53-40-I06	Rear Spar Bulkhead - BS 1245	53-40-I06-1	Rear Spar Side Fitting Inner Chord Splice	BS 1245, Ring Frame Splice at Stringer 12.5 and Stringer 21	2	53-746-01	53-746-01	53-746-01	May 2028	May 2028	September 2035
53-40-I06	Rear Spar Bulkhead - BS 1245	53-40-I06-2	Rear Spar Side Fitting	BS 1245, Inner Chord at Stringer 26	2	53-746-02	53-746-02	53-746-02	May 2028	May 2028	September 2035
53-40-I06	Rear Spar Bulkhead - BS 1245	53-40-I06-3	Rear Spar Side Fitting at Seat Track Attachment	BS 1245 at Stringer 27, Fastener in Inner Chord	2	53-746-03	53-746-03	53-746-03	May 2028	May 2028	September 2035



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
53-40-I07	Wheel Well Bulkhead - BS 1434 Crown/Side Frame	53-40-I07	Aft Wheel Well Bulkhead Inner Chord Splice	BS 1434, Upper Crown Slice at Top Centerline	2	53-747-01	53-747-01	53-747-01	May 2028	May 2028	September 2035
53-40-I14	Overwing Passenger Entry Door - Cutout Structure	53-40-I14A	Passenger Entry Overwing Door #3 Cutout	Upper and Lower corners at STA 1154 and 1204	1	-	-	53-748-01	January 2025	-	-
						-	-	53-748-02	January 2025	-	-
53-40-I14	Overwing Passenger Entry Door - Cutout Structure	53-40-I14B	Passenger Entry Overwing Door #3 Cutout	Edge Frame Inner Chord and Web at STA 1154.4 and 1204	2	-	-	53-749-01	May 2028	-	-
53-40-I14	Overwing Passenger Entry Door - Cutout Structure	53-40-I14C	Passenger Entry Overwing Door #3 Cutout	Edge Frame Inner Chord at STA 1154.4 and 1204	2	-	-	53-750-01	May 2028	-	-
53-40-I14	Overwing Passenger Entry Door - Cutout Structure	53-40-I14D	Passenger Entry Overwing Door #3 Cutout	Edge Frame Straps at STA 1154.4 and 1204	2	-	-	53-751-01	May 2028	-	-
53-40-I14	Overwing Passenger Entry Door - Cutout Structure	53-40-I14E	Passenger Entry Overwing Door #3 Cutout Upper Main Sill	Upper Main Sill, STA 1140 to 1180	2	-	-	53-752-01	May 2028	-	-
53-50-I04	Wheel Well Bulkhead - BS 1434	53-50-I04-1	Aft Wheel Well Bulkhead Side Fitting Inner Chord Splice	BS 1434, Splice at Stringer 21	2	53-753-01	53-753-01	53-753-01	May 2028	May 2028	September 2035
53-50-I04	Wheel Well Bulkhead - BS 1434	53-50-I04-2	Aft Wheel Well Bulkhead Side Fitting Outer Chord	BS 1434 From Stringer 28 to Stringer 45	2	53-753-02	53-753-02	53-753-02	May 2028	May 2028	September 2035
53-50-I04	Wheel Well Bulkhead - BS 1434	53-50-I04-3	Aft Wheel Well Bulkhead Side Fitting Outer Chord	BS 1434 Lower Splice at Stringer 35 Strap and Outer Chord at Fasteners	2	53-753-03	53-753-03	53-753-03	May 2028	May 2028	September 2035
						53-753-04	53-753-04	53-753-04	May 2028	May 2028	September 2035



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
53-50-I04	Wheel Well Bulkhead - BS 1434	53-50-I04-4	Aft Wheel Well Bulkhead Side Fitting Outer Chord	BS 1434 Lower Splice at Stringer 35 Outer Chord at Fasteners	1	53-753-05	53-753-05	53-753-05	January 2025	January 2025	September 2028
53-50-I04	Wheel Well Bulkhead - BS 1434	53-50-I04-5	Aft Wheel Well Bulkhead Horizontal Stiffeners (L/N 1-33)	Horizontal Stiffeners at WL 109 through 153, LBL5 - RBL5	2	53-753-06	-	-	-	-	-
53-50-I04	Wheel Well Bulkhead - BS 1434	53-50-I04-5	Aft Wheel Well Bulkhead Horizontal Stiffeners (L/N 34 and on)	Horizontal Stiffeners at WL 109 through 153, LBL5 - RBL5	2	53-753-07	53-753-07	53-753-07	May 2028	May 2028	September 2035
53-60-I01	Crown Panel, Skin and Stringer Section 46	53-60-I01	Crown Panel, Skin and Stringer Section 46	At Skin to Stringer Fastener Locations	2	53-754-01	53-754-01	-	-	-	-
53-60-I01	Crown Panel, Skin and Stringer Section 46	53-60-I01	Crown Panel, Skin and Stringer Section 46	At Skin to Stringer Fastener Locations	2	-	-	-	May 2028	May 2028	September 2035
53-60-I06	Circumferential Skin/Stringer Splice BS 1434	53-60-I06-1	Fuselage Circumferential Skin/Stringer Splice (L/N 75 - and on)	BS 1434, Bulkhead Outer Chord	1	53-754-02	53-754-02	-	-	January 2025	-
53-60-I06	Circumferential Skin/Stringer Splice BS 1434	53-60-I06-1	Fuselage Circumferential Skin/Stringer Splice	BS 1434, Bulkhead Outer Chord	1	-	-	53-754-05	January 2025	-	-
53-60-I06	Circumferential Skin/Stringer Splice BS 1434	53-60-I06-1	Fuselage Circumferential Skin/Stringer Splice	BS 1434, Bulkhead Outer Chord	1	-	-	-	-	-	September 2028
53-60-I06	Circumferential Skin/Stringer Splice BS 1434	53-60-I06-2	Fuselage Circumferential Skin/Stringer Splice (L/N 75 - and on)	BS 1434, Stringer End Fasteners	2	53-754-03	53-754-03	-	-	May 2028	-
53-60-I06	Circumferential Skin/Stringer Splice BS 1434	53-60-I06-2	Fuselage Circumferential Skin/Stringer Splice	BS 1434, Stringer End Fasteners	2	-	-	53-754-06	May 2028	-	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
53-60-I06	Circumferential Skin/Stringer Splice BS 1434	53-60-I06-2	Fuselage Circumferential Skin/Stringer Splice	BS 1434, Stringer End Fasteners	2	-	-	-	-	-	September 2035
53-60-I06	Circumferential Skin/Stringer Splice BS 1434	53-60-I06-3	Fuselage Circumferential Skin/Stringer Splice (L/N 75 - and on)	BS 1434, Paddle Fitting End Fasteners	2	53-754-04	53-754-04	-	-	May 2028	-
53-60-I06	Circumferential Skin/Stringer Splice BS 1434	53-60-I06-3	Fuselage Circumferential Skin/Stringer Splice	BS 1434, Paddle Fitting End Fasteners	2	-	-	53-754-07	May 2028	-	-
53-60-I06	Circumferential Skin/Stringer Splice BS 1434	53-60-I06-3	Fuselage Circumferential Skin/Stringer Splice	BS 1434, Paddle Fitting End Fasteners	2	-	-	-	-	-	September 2035
53-60-I07	Longitudinal Skin Lap Splices	53-60-I07A	Longitudinal Skin Lap Splices Inner Skin (L/N 1-422)	Section 46 Lap Splices at S-5	2	53-755-01	53-755-01	53-755-01	-	-	-
53-60-I07	Longitudinal Skin Lap Splices	53-60-I07A	Longitudinal Skin Lap Splices Inner Skin (L/N 423 and on)	Section 46 Lap Splices at S-5	2	53-755-02	53-755-02	53-755-02	May 2028	May 2028	September 2035
53-60-I07	Longitudinal Skin Lap Splices	53-60-I07A	Longitudinal Skin Lap Splices Inner Skin	All Section 46 Lap Splices except at S-5	2	53-755-03	53-755-03	53-755-03	May 2028	May 2028	September 2035
53-60-I07	Longitudinal Skin Lap Splices	53-60-I07B	Longitudinal Skin Lap Splices Outer Skin	Typical - All Section 46 Lap Splices	2	53-756-01	53-756-01	53-756-01	May 2028	May 2028	September 2035
53-60-I12	Entry Door - Cutout Structure	53-60-I12A	Passenger Entry Door #3 (-200)/#4 (-300) - Cutout	Section 46, Lower Corner @ STA 1497 and Upper Corner @ STA 1546.5	2	53-757-01	-	53-757-02	-	-	-
53-60-I12	Entry Door - Cutout Structure	53-60-I12A	Passenger Entry Door #3 (-200IGW) Cutout	Section 46, Lower Corner @ STA 1497 and Upper Corner @ STA 1546.5	FLS1	-	53-757-03	-	-	-	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
53-60-I12	Entry Door - Cutout Structure	53-60-I12A	Passenger Entry Door #3 (-200LR)/#4 (-300ER) - Cutout	Section 46, Lower Corner @ STA 1497 and Upper Corner @ STA 1546.5	FLS2	-	-	-	January 2025	January 2025	-
53-60-I12	Entry Door - Cutout Structure	53-60-I12A	Passenger Entry Door #3 (-200IGW/200LR) / #4 (-300ER) Cutout	Section 46, Lower Corner @ STA 1497 and Upper Corner @ STA 1546.5	FLS1	-	53-757-04	-	January 2022	January 2022	-
53-60-I12	Entry Door - Cutout Structure	53-60-I12B	Passenger Entry Door #3 (-200)/#4 (-300) Cutout	Edge Frames @ STA 1497 and STA 1546.5	2	53-758-01	53-758-01	53-758-01	May 2028	May 2028	-
53-60-I12	Entry Door - Cutout Structure	53-60-I12C	Passenger Entry Door #3 (-200)/#4 (-300) Cutout	Bear Strap	2	53-759-01	53-759-01	53-759-01	May 2028	May 2028	-
53-60-I12	Entry Door - Cutout Structure	53-60-I12D	Passenger Entry Door #3 (-200)/#4 (-300) Cutout	Upper Main Sill, STA 1540 to STA 1567	2	53-760-01	53-760-01	53-760-01	May 2028	May 2028	-
53-60-I12	Entry Door - Cutout Structure	53-60-I12E	Passenger Entry Door #3 (-200)/#4 (-300) Cutout	Lower Main Sill, STA 1476 to STA 1513.5	2	53-761-01	53-761-01	53-761-01	May 2028	May 2028	-
53-60-I14	Aft Standard Cargo Door - Cutout Structure	53-60-I14A	Small Cargo Door - Cutout Lower Main Sill	Body Station 1678.5	2	53-762-01	53-762-01	53-762-01	May 2028	May 2028	-
53-60-I14	Aft Standard Cargo Door - Cutout Structure	53-60-I14B	Small Cargo Door - Cutout Lower Main Sill	Body Station 1740 to 1769	2	53-763-01	53-763-01	53-763-01	May 2028	May 2028	-
53-60-I14	Aft Standard Cargo Door - Cutout Structure	53-60-I14C	Small Cargo Door - Cutout Inner Chord - Edge Frames - STA 1678.5 and STA 1754.5	Stringers at Door Stop Fittings	2	53-764-01	53-764-01	53-764-01	May 2028	May 2028	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
53-60-I14	Aft Standard Cargo Door - Cutout Structure	53-60-I14D	Small Cargo Door - Cutout Inner Chord - Edge Frames - STA 1678.5 and STA 1754.5	Stringers away from Door Stop Fittings	2	53-765-01	53-765-01	53-765-01	May 2028	May 2028	-
53-60-I14	Aft Standard Cargo Door - Cutout Structure	53-60-I14E	Small Cargo Door - Cutout Outer Chord - Edge Frames - STA 1678.5 and STA 1754.5	Stringers at Backup Fittings	2	53-766-01	53-766-01	53-766-01	May 2028	May 2028	-
53-60-I14	Aft Standard Cargo Door - Cutout Structure	53-60-I14F	Small Cargo Door - Cutout	Bear Strap	2	53-767-01	53-767-01	53-767-01	May 2028	May 2028	-
						53-767-02	53-767-02	53-767-02	May 2028	May 2028	-
53-60-I16	Aft Large Cargo Door - Cutout Structure	53-60-I16A	Aft Large Cargo Door - Cutout	Upper Corner @ STA 1790	2	53-768-01	53-768-01	53-768-01	May 2028	May 2028	September 2035
53-60-I16	Aft Large Cargo Door - Cutout Structure	53-60-I16B	Aft Large Cargo Door - Cutout Outer Chord - Upper Sill	Body Station 1683 to 1694	1	53-769-01	53-769-01	53-769-01	January 2025	January 2025	September 2028
53-60-I16	Aft Large Cargo Door - Cutout Structure	53-60-I16C	Aft Large Cargo Door - Upper Main Sill	STA 1769 to STA 1811	2	53-770-01	53-770-01	53-770-01	May 2028	May 2028	September 2035
53-60-I20	Main Deck Cargo Door - Cutout Structure	53-60-I20A	Main Deck Cargo Door - Cutout - Corners	Upper Corner, STA 1790; Upper Corner, STA 1637.5; Lower Corner STA 1637.5	1	-	-	-	-	-	September 2028
53-60-I20	Main Deck Cargo Door - Cutout Structure	53-60-I20D	Main Deck Cargo Door - Cutout Outer Chord Upper Sill	BS 1648 - 1673 & BS 1756 - 1780, S-6L	1	-	-	-	-	-	September 2028
53-70-I01	Crown Skin Panel - BS 1832 - 2150	53-70-I01	Crown Panel, Skin and Stringer Section 47	At Skin to Stringer Fastener Locations	2	-	-	-	-	-	September 2035



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
53-70-I04	Longitudinal Skin Lap Splices	53-70-I04A	Longitudinal Skin Lap Splices Inner Skin (L/N 1-422)	Section 47 Lap Splices at S-5	2	53-774-01	53-774-01	53-774-01	-	-	-
53-70-I04	Longitudinal Skin Lap Splices	53-70-I04A	Longitudinal Skin Lap Splices Inner Skin (L/N 423 and on)	Section 47 Lap Splices at S-5	2	53-774-02	53-774-02	53-774-02	May 2028	May 2028	September 2035
53-70-I04	Longitudinal Skin Lap Splices	53-70-I04A	Longitudinal Skin Lap Splices Inner Skin	All Section 47 Lap Splices except at S-5	2	53-774-03	53-774-03	53-774-03	May 2028	May 2028	September 2035
53-70-I04	Longitudinal Skin Lap Splices	53-70-I04B	Longitudinal Skin Lap Splices Outer Skin	Typical - All Section 47 Lap Splices	2	53-775-01	53-775-01	53-775-01	May 2028	May 2028	September 2035
53-70-I07	Entry Door - Cutout Structure	53-70-I07A	Passenger Entry Door #4 (-200)/#5 (-300) - Cutout	Edge Frames @ STA 2017 and STA 2067	2	53-776-01	53-776-01	53-776-01	May 2028	May 2028	-
53-70-I07	Entry Door - Cutout Structure	53-70-I07B	Passenger Entry Door #4 (-200)/#5 (-300) - Cutout	Bear Strap	2	53-777-01	53-777-01	53-777-01	May 2028	May 2028	-
53-70-I07	Entry Door - Cutout Structure	53-70-I07C	Passenger Entry Door #4 (-200)/#5 (-300) - Cutout	Section 47, Upper Sill, STA 2050	2	53-778-01	53-778-01	53-778-01	May 2028	May 2028	-
53-70-I07	Entry Door - Cutout Structure	53-70-I07D	Passenger Entry Door #4 (-200)/#5 (-300) - Cutout	Section 47, Lower Still, STA 2000 to STA 2017	2	53-779-01	53-779-01	53-779-01	May 2028	May 2028	-
53-70-I09	Bulk Cargo Door - Cutout Structure	53-70-I09	Bulk Cargo Door - Cutout Edge Frames	STA 1895 from Stringer S-33R to S-40R, STA 1937 from Stringer S-33R to S-35R	2	53-780-01	53-780-01	53-780-01	May 2028	May 2028	September 2035
53-80-I13	Pressure Bulkhead at STA 2150	53-80-I13A	Pressure Bulkhead at STA 2150; Sec 48 Lap Splice (L/N 1-3)(5 of 12 Lap Splices)	Gore Lap Splices - Web Surface Hidden Crack Fastener Row at Stiffener	1	53-781-01	-	-	-	-	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
53-80-I13	Pressure Bulkhead at STA 2150	53-80-I13A	Pressure Bulkhead at STA 2150; Sec 48 Lap Splice (L/N 1-422)	Gore Lap Splices - Web Surface Visible Crack Fastener Row at Stiffener	2	53-781-02	53-781-02	53-781-02	-	-	-
						53-781-03	53-781-03	53-781-03	-	-	-
53-80-I13	Pressure Bulkhead at STA 2150	53-80-I13A	Pressure Bulkhead at STA 2150; Sec 48 Lap Splice (L/N 423 and on)	Gore Lap Splices - Web Surface Visible Crack Fastener Row at Stiffener	2	53-781-04	53-781-04	53-781-04	May 2028	May 2028	September 2035
						53-781-05	53-781-05	53-781-05	May 2028	May 2028	September 2035
53-80-I13	Pressure Bulkhead at STA 2150	53-80-I13B	Pressure Bulkhead at STA 2150; Sec 48 Circumferential Crack in Web at Radial Stiffener	Entire Dome Between Super Tear Straps	2	53-782-01	53-782-01	53-782-01	May 2028	May 2028	September 2035
53-80-I13	Pressure Bulkhead at STA 2150	53-80-I13C	Pressure Bulkhead, STA 2150, Dome Web Attachment to Y-Ring (L/N 1-422)	Entire Dome Web Between Stiffeners	2	53-783-01	53-783-01	53-783-01	-	-	-
53-80-I13	Pressure Bulkhead at STA 2150	53-80-I13C	Pressure Bulkhead, STA 2150, Dome Web Attachment to Y-Ring (L/N 423 and on)	Entire Dome Web Between Stiffeners	2	53-783-02	53-783-02	53-783-02	May 2028	May 2028	September 2035
53-80-I14	Pivot Bulkhead - BS 2370	53-80-I14A	Stabilizer Pivot Bulkhead STA 2370	Vertical Stiffener at BL 36.5	2	53-784-01	53-784-01	53-784-01	May 2028	May 2028	September 2035
53-80-I14	Pivot Bulkhead - BS 2370	53-80-I14B	Stabilizer Pivot Bulkhead STA 2370 - Vertical Stiffeners	LH/RH Upper/Lower corner of cutout, BS 2370, LBL/RBL 15, WL 230/280	1	53-785-01	53-785-01	53-785-01	January 2025	January 2025	September 2028
53-80-I15	Stabilizer Pivot Fittings & Backup Fittings	53-80-I15	Stabilizer Pivot Fitting Lug; Section 48	Station 2365	2	53-786-01	53-786-01	53-786-01	May 2028	May 2028	September 2035



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
53-80-I17	Jackscrew Fittings - BS 2245	53-80-I17	Jackscrew Support Fitting Lug	Section 48 Fin Support - Station 2245	2	53-787-01	53-787-01	53-787-01	May 2028	May 2028	September 2035
54-51-I01	Strut-to-Wing Attachments	54-51-I01i	Aft Upper Spar Fitting R4 (GE)	Horizontal Flange First Fastener	FLS1	-	-	-	January 2022	January 2022	-
54-51-I02	Strut Upper Spar	54-51-I02A	Aft Upper Spar Chord Splice (PW)	Fasteners Common to the Chord, Splice and Side Skin from NTSA 298-308	1	54-701-02	54-701-02	54-701-02	-	-	-
54-51-I02	Strut Upper Spar	54-51-I02D	Strut Upper Spar (PW)	Upper Spar Left and Right Sides From NSTA 245 - NSTA 292	1	54-702-02	-	-	-	-	-
54-51-I02	Strut Upper Spar	54-51-I02D	Strut Upper Spar (PW)	Upper Spar Left and Right Sides From NSTA 245 - NSTA 292	1	-	54-702-03	-	-	-	-
54-51-I02	Strut Upper Spar	54-51-I02D	Strut Upper Spar (PW)	Forward Chords between NSTA 245 and 292 Left and Right	1	-	-	54-702-04	-	-	-
54-51-I02	Strut Upper Spar	54-51-I02B	Upper Spar Bay 3 (GE)	Upper Spar Between NSTA 230 and NSTA 245	1	54-710-02	54-710-03	-	-	-	-
54-51-I02	Strut Upper Spar	54-51-I02B	Upper Spar Bay 3 (GE)	Upper Spar Between NSTA 230 and NSTA 245	1	-	54-710-04	-	-	-	-
54-51-I02	Strut Upper Spar	54-51-I02E	Strut Upper Spar Bay 5/6 at Cutout (GE)	Upper Spar in Bay 5/6 at Cutout NSTA 268 to NSTA 293	1	54-711-02	-	-	-	-	-
54-51-I02	Strut Upper Spar	54-51-I02E	Strut Upper Spar Bay 5/6 at Cutout (GE)	Upper Spar in Bay 5/6 at Cutout NSTA 268 to NSTA 293	1	-	54-711-03	-	-	-	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
54-51-I02	Strut Upper Spar	54-51-I02E	Strut Upper Spar Bay 5/6 at Cutout (GE)	Upper Spar in Bay 5/6 at Cutout NSTA 268 to NSTA 293	1	-	54-711-04	-	-	-	-
54-51-I02	Strut Upper Spar	54-51-I02F	Strut Upper Spar Bay 5 at Cutout (GE)	Side Skin in Bay 5 at Cutout NSTA 268 to NSTA 277	1	54-712-02	-	-	-	-	-
54-51-I02	Strut Upper Spar	54-51-I02F	Strut Upper Spar Bay 5 at Cutout (GE)	Side Skin in Bay 5 at Cutout NSTA 268 to NSTA 277	1	-	54-712-03	-	-	-	-
54-51-I02	Strut Upper Spar	54-51-I02F	Strut Upper Spar Bay 5 at Cutout (GE)	Side Skin in Bay 5 at Cutout NSTA 268 to NSTA 277	1	-	54-712-04	-	-	-	-
54-51-I02	Strut Upper Spar	54-51-I02T	Strut Upper Spar Bay 6 at Cutout (GE)	Side Skin in Bay 6 at Cutout NSTA 283 to NSTA 293	1	54-713-02	-	-	-	-	-
54-51-I02	Strut Upper Spar	54-51-I02T	Strut Upper Spar Bay 6 at Cutout (GE)	Side Skin in Bay 6 at Cutout NSTA 283 to NSTA 293	1	-	54-713-03	-	-	-	-
54-51-I02	Strut Upper Spar	54-51-I02T	Strut Upper Spar Bay 6 at Cutout (GE)	Side Skin in Bay 6 at Cutout NSTA 283 to NSTA 293	1	-	54-713-04	-	-	-	-
54-51-I02	Strut Upper Spar	54-51-I02R	Upper Spar (GE)	Fasteners Common to Upper Chord, Web, Frames, @ NSTA 213/230/245/265/280/295	1	54-714-02	-	-	-	-	-
54-51-I02	Strut Upper Spar	54-51-I02R	Upper Spar (GE)	Fasteners Common to Upper Chord, Web, Frames, @ NSTA 213/230/245/265/280/295	1	-	54-714-03	-	-	-	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
54-51-I02	Strut Upper Spar	54-51-I02S	Upper Spar (GE)	Fastener Common to the Upper Chord and Web Between Frames at NSTA 245 and NSTA 265	1	54-715-02	54-715-02	-	-	-	-
54-51-I02	Strut Upper Spar	54-51-I02a	Strut Upper Spar Bay 2 (GE)	RH Web/Chord/Skin Between NS 213-230	1	-	-	-	January 2025	January 2025	September 2028
54-51-I02	Strut Upper Spar	54-51-I02b	Strut Upper Spar Bay 3 (GE)	LH and RH Chord and Web, NSTA 232-240	1	-	-	-	January 2025	January 2025	-
54-51-I02	Strut Upper Spar	54-51-I02B	Strut Upper Spar Bay 3 (GE)	LH and RH Chord and Web, NSTA 232-240	1	-	-	-	-	-	September 2028
54-51-I02	Strut Upper Spar	54-51-I02c	Strut Upper Spar Bay 3 (GE)	Web Cutout at Sta 235-240	1	-	-	-	January 2025	January 2025	-
54-51-I02	Strut Upper Spar	54-51-I02e	Strut Upper Spar Bay 5 (GE)	Bay 5 Cutout Between NSTA 268 and NSTA 277	FLS1	-	-	-	January 2022	January 2022	-
54-51-I02	Strut Upper Spar	54-51-I02e	Strut Upper Spar Bay 5 (GE)	Bay 5 Cutout Between NSTA 268 and NSTA 277	FLS1	-	-	-	January 2022	January 2022	-
54-51-I02	Strut Upper Spar	54-51-I02e	Strut Upper Spar Bay 5 (GE)	Bay 5 Cutout Between NSTA 268 and NSTA 277	FLS1	-	-	-	-	-	May 2023
54-51-I02	Strut Upper Spar	54-51-I02e	Strut Upper Spar Bay 5 (GE)	Bay 5 Cutout Between NSTA 268 and NSTA 277	FLS1	-	-	-	-	-	May 2023
54-51-I02	Strut Upper Spar	54-51-I02f	Strut Upper Spar Bay 6 (GE)	Side Skin Between NSTA 281 and NSTA 292	FLS1	-	-	-	January 2022	January 2022	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
54-51-I02	Strut Upper Spar	54-51-I02f	Strut Upper Spar Bay 6 (GE)	Side Skin Between NSTA 281 and NSTA 292	FLS1	-	-	-	January 2022	January 2022	-
54-51-I02	Strut Upper Spar	54-51-I02f	RHS Upper Spar Bay 6 (GE)	Side Skin Between NSTA 281 and NSTA 292	FLS1	-	-	-	-	-	May 2023
54-51-I02	Strut Upper Spar	54-51-I02f	RHS Upper Spar Bay 6 (GE)	Side Skin Between NSTA 281 and NSTA 292	FLS1	-	-	-	-	-	May 2023
54-51-I02	Strut Upper Spar	54-51-I02i	Strut Upper Spar (GE)	Upper Chord Splice Between NSTA 305 and NSTA 315	1	-	-	-	January 2025	January 2025	-
54-51-I02	Strut Upper Spar	54-51-I02i	Strut Upper Spar (GE)	Upper Chord Splice Between NSTA 305 and NSTA 315	FLS1	-	-	-	-	-	May 2023
54-51-I02	Strut Upper Spar	54-51-I02m	Strut Upper Spar (GE)	R3/R4 Fitting Inboard Flange	FLS1	-	-	-	January 2022	January 2022	-
54-51-I02	Strut Upper Spar	54-51-I02m	Strut Upper Spar (GE)	R3/R4 Fitting Inboard Flange	FLS1	-	-	-	January 2022	January 2022	-
54-51-I02	Strut Upper Spar	54-51-I02m	Strut Aft Upper Spar (GE)	R3/R4 Fitting Inboard Flange	FLS1	-	-	-	-	-	May 2023
54-51-I02	Strut Upper Spar	54-51-I02m	Strut Aft Upper Spar (GE)	R3/R4 Fitting Inboard Flange	FLS1	-	-	-	-	-	May 2023
54-51-I02	Strut Upper Spar	54-51-I02p	Strut Upper Spar (GE)	R1 Fitting Attachment NSTA 225 to NSTA 268	1	-	-	-	January 2025	January 2025	-
54-51-I02	Strut Upper Spar	54-51-I02p	Pylon R1/Web Interface (GE)	R1 Fitting - NSTA 188 to NSTA 314	1	-	-	-	-	-	September 2028
54-51-I02	Strut Upper Spar	54-51-I02u	Pylon R1/Web Interface (GE)	R1 Fitting - NSTA 188 to NSTA 314	1	-	-	-	-	-	September 2028



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
54-51-I02	Strut Upper Spar	54-51-I02v	Pylon R1/Web Interface (GE)	R1 Fitting - NSTA 188 to NSTA 314	1	-	-	-	-	-	September 2028
54-51-I02	Strut Upper Spar	54-51-I02w	Pylon R1/Web Interface (GE)	R1 Fitting - NSTA 188 to NSTA 314	1	-	-	-	-	-	September 2028
54-51-I02	Strut Upper Spar	54-51-I02r	Upper Spar Assembly (GE)	Upper Spar Common to Frames/Bulkheads	1	-	-	-	January 2025	January 2025	-
54-51-I02	Strut Upper Spar	54-51-I02r	Upper Spar Assembly (GE)	Upper Spar Common to Frames/Bulkheads	1	-	-	-	-	-	September 2028
54-51-I02	Strut Upper Spar	54-51-I02s	Upper Spar Assembly (Bay 4) (GE)	NSTA 245 to NSTA 264.6	FLS1	-	-	-	January 2022	January 2022	-
54-51-I02	Strut Upper Spar	54-51-I02s	Upper Spar Assembly (Bay 4) (GE)	NSTA 245 to NSTA 264.6	FLS1	-	-	-	January 2022	January 2022	-
54-51-I02	Strut Upper Spar	54-51-I02s	Upper Spar Assembly (Bay 4) (GE)	NSTA 245 to NSTA 265	1	-	-	-	-	-	September 2028
54-51-I02	Strut Upper Spar	54-51-I02A	Upper Spar Chord (RR)	Upper Spar Chord Splice Plate at NSTA 313 to NSTA 323	1	54-773-01	54-773-01	54-773-01	-	-	-
54-51-I02	Strut Upper Spar	54-51-I02C	Forward Upper Spar (RR)	Upper Spar at Frame/Bulkheads	1	54-774-01	54-774-01	54-774-01	-	-	-
54-51-I02	Strut Upper Spar	54-51-I02D	Forward Upper Spar (RR)	Fasteners Common to the Upper Chord and Web, NSTA 223 to NSTA 294, non-frame locations	1	54-775-01	54-775-01	54-775-01	-	-	-
54-51-I03	Strut Side Skins	54-51-I03B	Strut Side Skin (PW)	Cutout at NSTA 317 to NSTA 330 on Left and Right Side Skins	1	54-703-02	-	-	-	-	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
54-51-I03	Strut Side Skins	54-51-I03B	Strut Side Skin (PW)	Cutout at NSTA 317 to NSTA 330 on Left and Right Side Skins	FLS1	-	54-703-03	-	-	-	-
54-51-I03	Strut Side Skins	54-51-I03B	Strut Side Skin (PW)	Cutout at NSTA 317 to NSTA 330 on Left and Right Side Skins	FLS1	-	54-703-04	-	-	-	-
54-51-I03	Strut Side Skins	54-51-I03B	Strut Side Skin (PW)	Pressure Relief Door Cutout between NSTA 317 and 330	1	-	-	54-703-05	-	-	-
54-51-I03	Strut Side Skins	54-51-I03B	Side Skin Cutout (GE)	Side Skin Cutout, NSTA 310 to NSTA 325	1	54-716-01	-	-	-	-	-
					FLS1	-	54-716-02	-	-	-	-
54-51-I03	Strut Side Skins	54-51-I03B	Side Skin Cutout (GE)	Side Skin Cutout, NSTA 310 to NSTA 325	FLS1	-	54-713-03	-	-	-	-
54-51-I03	Strut Side Skins	54-51-I03a	Side Skin Cutout, Bay 8 (GE)	Cutout at Bay 8	FLS1	-	-	-	-	-	May 2023
54-51-I03	Strut Side Skins	54-51-I03b	Side Skin Cutout, Bay 8 (GE)	NSTA 310 to NSTA 325	FLS1	-	-	-	January 2022	January 2022	-
54-51-I03	Strut Side Skins	54-51-I03b	Side Skin Cutout, Bay 8 (GE)	Cutout at Bay 8	FLS1	-	-	-	-	-	May 2023
54-51-I03	Strut Side Skins	54-51-I03b	Side Skin Cutout, Bay 8 (GE)	Cutout at Bay 8	FLS1	-	-	-	-	-	May 2023
54-51-I03	Strut Side Skins	54-51-I03c	Side Skin Cutout, Bay 8 (GE)	NSTA 310 to NSTA 325	FLS1	-	-	-	January 2022	January 2022	-
54-51-I03	Strut Side Skins	54-51-I03C	Side Skin Cutout, Bay 8 (GE)	Cutout at Bay 8	FLS1	-	-	-	-	-	May 2023



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
54-51-I03	Strut Side Skins	54-51-I03e	Pylon Side Skin (GE)	Side Skin Between NSTA 267 and NSTA 278	1	-	-	-	-	-	September 2028
54-51-I03	Strut Side Skins	54-51-I03v	Pylon Side Skin (GE)	Side Skin Between NSTA 267 and NSTA 278	1	-	-	-	-	-	September 2028
54-51-I03	Strut Side Skins	54-51-I03g	Strut Side Skin Bay 4 (GE)	NSTA 245 to NSTA 264.6	FLS1	-	-	-	January 2022	January 2022	-
54-51-I03	Strut Side Skins	54-51-I03g	Strut Side Skin Bay 4 (GE)	NSTA 245 to NSTA 264.6	FLS1	-	-	-	January 2022	January 2022	-
54-51-I03	Strut Side Skins	54-51-I03g	Pylon Side Skin (GE)	Side Skin Between NSTA 247 and NSTA 263	1	-	-	-	-	-	September 2028
54-51-I03	Strut Side Skins	54-51-I03w	Pylon Chord (GE)	Upper Spar Chord Between NSTA 247 and NSTA 263	1	-	-	-	-	-	September 2028
54-51-I03	Strut Side Skins	54-51-I03x	Pylon Side Skin (GE)	Side Skin Between NSTA 247 and NSTA 263	1	-	-	-	-	-	September 2028
54-51-I03	Strut Side Skins	54-51-I03i	Side Skin Cutout (Bay 3) (GE)	NSTA 230 to 245	FLS1	-	-	-	January 2022	January 2022	-
54-51-I03	Strut Side Skins	54-51-I03i	Side Skin Cutout (Bay 3) (GE)	NSTA 230 to 245	FLS1	-	-	-	January 2022	January 2022	-
54-51-I03	Strut Side Skins	54-51-I03l	GE90-115B Side Skin Cutout (Bay 3) (GE)	NSTA 230 to NSTA 245	1	-	-	-	-	-	September 2028
54-51-I03	Strut Side Skins	54-51-I03j	Side Skin Cutout (Bay 2) (GE)	NSTA 213.5 to NSTA 230	FLS1	-	-	-	January 2022	January 2022	-
54-51-I03	Strut Side Skins	54-51-I03j	Side Skin Cutout (Bay 2) (GE)	NSTA 213.5 to NSTA 230	FLS1	-	-	-	January 2022	January 2022	-
54-51-I03	Strut Side Skins	54-51-I03j	Side Skin Cutout Bay 2 (GE)	NSTA 213.5 to NSTA 230.0, Skin and Upper Spar Chord	FLS1	-	-	-	-	-	May 2023



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
54-51-I03	Strut Side Skins	54-51-I03j	Side Skin Cutout Bay 2 (GE)	NSTA 213.5 to NSTA 230.0, Skin and Upper Spar Chord	FLS1	-	-	-	-	-	May 2023
54-51-I03	Strut Side Skins	54-51-I03k	Side Skin Cutout Bay 2 (GE)	NSTA 213.5 to NSTA 230	FLS1	-	-	-	January 2022	January 2022	-
54-51-I03	Strut Side Skins	54-51-I03k	Side Skin Cutout Bay 2 (GE)	NSTA 213.5 to NSTA 230.0, Skin and Upper Spar Chord	FLS1	-	-	-	-	-	May 2023
54-51-I03	Strut Side Skins	54-51-I03k	Side Skin Cutout Bay 2 (GE)	NSTA 213.5 to NSTA 230.0, Skin and Upper Spar Chord	FLS1	-	-	-	-	-	May 2023
54-51-I03	Strut Side Skins	54-51-I03s	Strut LH Side Skin Bay 4 (GE)	NSTA 245 to NSTA 264.6, LHS	FLS1	-	-	-	January 2022	January 2022	-
54-51-I03	Strut Side Skins	54-51-I03s	Strut LH Side Skin Bay 4 (GE)	NSTA 245 to NSTA 264.6, LHS	FLS1	-	-	-	January 2022	January 2022	-
54-51-I03	Strut Side Skins	54-51-I03s	Bay 4 Upper Spar (GE)	LHS NSTA 245 to NSTA 264	1	-	-	-	-	-	September 2028
54-51-I04	Strut Lower Spar	54-51-I04A	Lower Spar Chord (PW)	Spar Chord from NSTA 242 to NSTA 248	1	54-704-02	-	-	-	-	-
54-51-I04	Strut Lower Spar	54-51-I04A	Lower Spar Chord (PW)	Spar Chord from NSTA 242 to NSTA 248	1	-	54-704-03	-	-	-	-
54-51-I04	Strut Lower Spar	54-51-I04A	Lower Spar (PW)	Spar Chord from NSTA 242 to NSTA 248	1	-	-	54-704-04	-	-	-
54-51-I04	Strut Lower Spar	54-51-I04D	Lower Spar (PW)	Fastener Locations on Lower Spar Common to Web and Chord, NSTA 261-281	1	54-705-01	-	-	-	-	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
54-51-I04	Strut Lower Spar	54-51-I04D	Lower Spar (PW)	Fastener Locations on Lower Spar Common to Web and Chord, NSTA 261-281	1	-	54-705-03	-	-	-	-
54-51-I04	Strut Lower Spar	54-51-I04D	Lower Spar (PW)	Fastener Locations on Lower Spar Common to Web and Chord, NSTA 261-281	1	-	-	54-705-03	-	-	-
54-51-I04	Strut Lower Spar	54-51-I04F	Lower Spar @ AEMB (PW)	At Fasteners Common to Chord, Web, AEMB - Fwd and Aft of the Mount Attach Holes	1	54-706-01	-	-	-	-	-
54-51-I04	Strut Lower Spar	54-51-I04F	Lower Spar @ AEMB (PW)	At Fasteners Common to Chord, Web, AEMB - Fwd and Aft of the Mount Attach Holes	1	-	54-706-03	-	-	-	-
54-51-I04	Strut Lower Spar	54-51-I04F	Strut Lower Spar (PW)	Spar Chord at Aft Engine Mount Bulkhead between NSTA 298 and 310	1	-	-	54-706-04	-	-	-
54-51-I04	Strut Lower Spar	54-51-I04A	Lower Spar Bay 3 (GE)	Bay 3 Fasteners Common to the Chord Between Frames at NSTA 230 and 245	1	54-717-02	-	-	-	-	-
54-51-I04	Strut Lower Spar	54-51-I04A	Lower Spar Bay 3 (GE)	Bay 3 Fasteners Common to the Chord Between Frames at NSTA 230 and 245	FLS1	-	54-717-03	-	-	-	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
54-51-I04	Strut Lower Spar	54-51-I04A	Lower Spar Bay 3 (GE)	Bay 3 Fasteners Common to the Chord Between Frames at NSTA 230 and 245	FLS1	-	54-717-04	-	-	-	-
54-51-I04	Strut Lower Spar	54-51-I04B	Lower Outboard Spar Chord at Aft Engine Mount Bulkhead (GE)	Lower Spar at Aft Engine Mount, NSTA 303 to NSTA 317	1	54-718-02	54-718-02	-	-	-	-
54-51-I04	Strut Lower Spar	54-51-I04J	Lower Spar @ Cutout (GE)	Bay 2 Fasteners Common to the Chord and Web Between NSTA 212 and NSTA 230	1	54-719-02	54-719-02	-	-	-	-
54-51-I04	Strut Lower Spar	54-51-I04M	Lower Spar (GE)	Frames NSTA 213, 230, 245, 265, 280, and 295, LH and RH Sides	1	54-720-01	-	-	-	-	-
54-51-I04	Strut Lower Spar	54-51-I04M	Lower Spar (GE)	Frame NSTA 213, 230, 245, 265, 280, and 295, LH and RH Side	1	-	54-720-03	-	-	-	-
54-51-I04	Strut Lower Spar	54-51-I04a	Strut Lower Chord (GE)	Bays 2 and 3 RH Chord/Web, NSTA at 213-245	FLS1	-	-	-	January 2022	January 2022	-
54-51-I04	Strut Lower Spar	54-51-I04a	Strut Lower Chord (GE)	Bays 2 and 3 RH Chord/Web, NSTA at 213-245	FLS1	-	-	-	January 2022	January 2022	-
54-51-I04	Strut Lower Spar	54-51-I04a	Lower Spar Bay 3 (GE)	Lower Spar Between NSTA 230 and 245	FLS11	-	-	-	-	-	May 2023
54-51-I04	Strut Lower Spar	54-51-I04a	Lower Spar Bay 3 (GE)	Lower Spar Between NSTA 230 and 245	FLS1	-	-	-	-	-	May 2023



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
54-51-I04	Strut Lower Spar	54-51-I04b	Strut Lower Chord Bay 3 (GE)	LH Chord Between NSTA 230 and 245	FLS1	-	-	-	January 2022	January 2022	-
54-51-I04	Strut Lower Spar	54-51-I04b	Strut Lower Chord Bay 3 (GE)	LH Chord Between NSTA 230 and NSTA 245	FLS1	-	-	-	-	-	May 2023
54-51-I04	Strut Lower Spar	54-51-I04b	Strut Lower Chord Bay 3 (GE)	LH Chord Between NSTA 230 and NSTA 245	FLS1	-	-	-	-	-	May 2023
54-51-I04	Strut Lower Spar	54-51-I04c	Strut Lower Spar (GE)	Bay 3 Lower Spar Web Cutout	FLS1	-	-	-	January 2022	January 2022	-
54-51-I04	Strut Lower Spar	54-51-I04c	Strut Lower Spar (GE)	Bay 3 Lower Spar Web Cutout	FLS1	-	-	-	January 2022	January 2022	-
54-51-I04	Strut Lower Spar	54-51-I04d	Strut Lower Spar (GE)	Bays 5, 6 and 7 LH Chord/Web, NSTA 264-309	FLS1	-	-	-	January 2022	January 2022	-
54-51-I04	Strut Lower Spar	54-51-I04d	Pylon Lower Spar (GE)	LH Chord/Skin/Web Joint Between NSTA 266 and NSTA 278.5	FLS1	-	-	-	-	-	May 2023
54-51-I04	Strut Lower Spar	54-51-I04s	Pylon Side Skin (GE)	LH Chord/Skin/Web Joint Between NSTA 266 and NSTA 278.5	FLS1	-	-	-	-	-	May 2023
54-51-I04	Strut Lower Spar	54-51-I04s	Pylon Side Skin (GE)	LH Chord/Skin/Web Joint Between NSTA 266 and NSTA 278.5	FLS1	-	-	-	-	-	May 2023
54-51-I04	Strut Lower Spar	54-51-I04e	Pylon Lower Spar (GE)	RH Chord/Skin/Web Joint Between NSTA 266 and NSTA 278.5	FLS1	-	-	-	-	-	May 2023



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
54-51-I04	Strut Lower Spar	54-51-I04e	Pylon Lower Spar (GE)	RH Chord/Skin/Web Joint Between NSTA 266 and NSTA 278.5	FLS1	-	-	-	-	-	May 2023
54-51-I04	Strut Lower Spar	54-51-I04t	Pylon Side Skin (GE)	RH Chord/Skin/Web Joint Between NSTA 266 and NSTA 278.5	FLS1	-	-	-	-	-	May 2023
54-51-I04	Strut Lower Spar	54-51-I04t	Pylon Side Skin (GE)	RH Chord/Skin/Web Joint Between NSTA 266 and NSTA 278.5	FLS1	-	-	-	-	-	May 2023
54-51-I04	Strut Lower Spar	54-51-I04f	Pylon Lower Spar (GE)	Bay 5 Lwr Spar Web Cutout	FLS1	-	-	-	-	-	May 2023
54-51-I04	Strut Lower Spar	54-51-I04f	Pylon Lower Spar (GE)	Bay 5 Lwr Spar Web Cutout	FLS1	-	-	-	-	-	May 2023
54-51-I04	Strut Lower Spar	54-51-I04g	Strut Lower Spar (GE)	Chord at Aft Engine Mount Bulkhead NSTA 303 to NSTA 317	1	-	-	-	January 2025	January 2025	September 2028
54-51-I04	Strut Lower Spar	54-51-I04h	RHS Lower Spar Chord-Web-Skin Joint (GE)	Bay 2, STA 213 to STA 230	FLS1	-	-	-	-	-	May 2023
54-51-I04	Strut Lower Spar	54-51-I04h	RHS Lower Spar Chord-Web-Skin Joint (GE)	Bay 2, STA 213 to STA 230	FLS1	-	-	-	-	-	May 2023
54-51-I04	Strut Lower Spar	54-51-I04j	Strut Lower Spar (GE)	Bays 2 and 3 LH Chord NSTA 213-245	FLS1	-	-	-	January 2022	January 2022	-
54-51-I04	Strut Lower Spar	54-51-I04j	Strut Lower Spar (GE)	Bays 2 and 3 LH Chord NSTA 213-245	FLS1	-	-	-	January 2022	January 2022	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
54-51-I04	Strut Lower Spar	54-51-I04j	LHS Lower Spar Chord-web-skin Joint (GE)	Bay 2	FLS1	-	-	-	-	-	May 2023
54-51-I04	Strut Lower Spar	54-51-I04j	LHS Lower Spar Chord-web-skin Joint (GE)	Bay 2	FLS1	-	-	-	-	-	May 2023
54-51-I04	Strut Lower Spar	54-51-I04I	Strut Lower Spar Bay 4 (GE)	NSTA 245 to NSTA 264LHS and RHS Lower Spar	1	-	-	-	January 2025	January 2025	-
54-51-I04	Strut Lower Spar	54-51-I04I	Lower Spar Bay 4 (GE)	NSTA 245 to NSTA 264LHS and RHS Lower Spar	FLS1	-	-	-	-	-	May 2023
54-51-I04	Strut Lower Spar	54-51-I04I	Lower Spar Bay 4 (GE)	NSTA 245 to NSTA 264LHS and RHS Lower Spar	FLS1	-	-	-	-	-	May 2023
54-51-I04	Strut Lower Spar	54-51-I04u	Lower Spar Bay 4 (GE)	NSTA 245 to NSTA 264LHS and RHS Lower Spar	FLS1	-	-	-	-	-	May 2023
54-51-I04	Strut Lower Spar	54-51-I04u	Lower Spar Bay 4 (GE)	NSTA 245 to NSTA 264LHS and RHS Lower Spar	FLS1	-	-	-	-	-	May 2023
54-51-I04	Strut Lower Spar	54-51-I04m	Strut Lower Spar (GE)	Chord STA at Bulkhead	FLS1	-	-	-	January 2022	January 2022	May 2023
54-51-I04	Strut Lower Spar	54-51-I04m	Strut Lower Spar (GE)	Chord STA at Bulkhead	FLS1	-	-	-	January 2022	January 2022	May 2023
54-51-I04	Strut Lower Spar	54-51-I04r	Strut Lower Spar (GE)	Bays 5, 6, and 7 NSTA 264-309	FLS1	-	-	-	January 2022	January 2022	-
54-51-I04	Strut Lower Spar	54-51-I04r	Lower Spar Chords/Web Bays 6-7 (GE)	Lower Spar Chord Joint Between NSTA 280 and NSTA 308	FLS1	-	-	-	-	-	May 2023



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
54-51-I04	Strut Lower Spar	54-51-I04r	Lower Spar Chords/Web Bays 6-7 (GE)	Lower Spar Chord Joint Between NSTA 280 and NSTA 308	FLS1	-	-	-	-	-	May 2023
54-51-I04	Strut Lower Spar	54-51-I04A	Lower Chord (RR)	Lower Chord, Web at Aft Engine Mount Attachment Bolt Holes at NSTA 307.7, 309.9, 313.3, and 315.5	1	54-776-01	54-776-01	54-776-01	-	-	-
54-51-I04	Strut Lower Spar	54-51-I04B	Aft Lower Chord at Aft Engine Mount Bulkhead (RR)	Fasteners Common to Chord and Web under Engine Mount Fitting, NSTA 305 to NSTA 317	1	54-777-01	54-777-01	-	-	-	-
54-51-I04	Strut Lower Spar	54-51-I04B	Aft Lower Spar Chord Under Engine Mount Bulkhead (RR)	Fasteners Common to Chord and Web under Engine Mount Fitting, NSTA 305 to NSTA 317	1	-	-	54-777-02	-	-	-
54-51-I05	Strut Forward Engine Mount Bulkhead	54-51-I05D	Forward Engine Mount Bulkhead (PW)	Forward Flange @ 1.188 IN. Diameter GSE Holes, T = .45	1	54-707-01	-	-	-	-	-
54-51-I05	Strut Forward Engine Mount Bulkhead	54-51-I05D	Forward Engine Mount Bulkhead (PW)	Forward Flange @ 1.188 IN. Diameter GSE Holes, T = .60	1	54-707-03	-	-	-	-	-
54-51-I05	Strut Forward Engine Mount Bulkhead	54-51-I05D	Forward Engine Mount Bulkhead (PW)	Forward Flange at GSE Holes; T = .60	1	-	54-707-04	-	-	-	-
54-51-I05	Strut Forward Engine Mount Bulkhead	54-51-I05D	Strut Forward Engine Mount Bulkhead Assembly (PW)	Front Flange at open GSE Holes	1	-	-	54-707-05	-	-	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
54-51-I05	Strut Forward Engine Mount Bulkhead	54-51-I05A	Forward Engine Mount Bulkhead (GE)	Tension Fitting Gusset at NSTA 186.65	1	54-721-01	54-721-01	-	-	-	-
54-51-I05	Strut Forward Engine Mount Bulkhead	54-51-I05a	Strut Fwd Engine Mount Bulkhead (GE)	Gusset Edge	1	-	-	-	January 2025	January 2025	-
54-51-I05	Strut Forward Engine Mount Bulkhead	54-51-I05a	Strut Fwd Engine Mount Bulkhead (GE)	Gusset Upper Edge	1	-	-	-	-	-	September 2028
54-51-I05	Strut Forward Engine Mount Bulkhead	54-51-I05b	Strut Fwd Engine Mount Bulkhead (GE)	Tension Fitting	1	-	-	-	January 2025	January 2025	-
54-51-I05	Strut Forward Engine Mount Bulkhead	54-51-I05b	Fwd Engine Mount Bulkhead (GE)	Tension Fitting	1	-	-	-	-	-	September 2028
54-51-I05	Strut Forward Engine Mount Bulkhead	54-51-I05A	Forward Engine Mount Bulkhead (RR)	Fwd Engine Mount Bulkhead Tension Fitting End Pad	1	54-778-01	54-778-01	-	-	-	-
54-51-I05	Strut Forward Engine Mount Bulkhead	54-51-I05A	Forward Engine Mount Bulkhead (RR)	Fwd Engine Mount Bulkhead Tension Fitting End Pad	1	-	-	54-778-01	-	-	-
54-51-I06	Strut Nacelle STA 273 Bulkhead	54-51-I06a	Strut Mid Bulkhead STA 295 (GE)	Flange	FLS1	-	-	-	January 2022	January 2022	May 2023
54-51-I06	Strut Nacelle STA 273 Bulkhead	54-51-I06a	Strut Mid Bulkhead STA 295 (GE)	Flange	FLS1	-	-	-	January 2022	January 2022	May 2023
54-51-I06	Strut Nacelle STA 273 Bulkhead	54-51-I06b	Strut Mid Bulkhead STA 295 (GE)	R1 Attachment Pad @ Bolt Hole	1	-	-	-	January 2025	January 2025	September 2028
54-51-I06	Strut Nacelle STA 273 Bulkhead	54-51-I06A	Aft Engine Mount Bulkhead (RR)	R1 Fitting Attach Tension Fitting	1	54-779-01	-	-	-	-	-
54-51-I06	Strut Nacelle STA 273 Bulkhead	54-51-I06A	Aft Engine Mount Bulkhead (RR)	R1 Fitting Attach Tension Fitting	1	-	54-779-03	-	-	-	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
54-51-I06	Strut Nacelle STA 273 Bulkhead	54-51-I06A	Aft Engine Mount Bulkhead (RR)	Upper Tension (Bathtub) Fitting End Pad	1	-	-	54-779-02	-	-	-
54-51-I07	Strut Aft Engine Mount Bulkhead	54-51-I07a	Strut Aft Engine Mount Bulkhead (GE)	R1 Fitting Attachment	1	-	-	-	January 2025	January 2025	-
54-51-I07	Strut Aft Engine Mount Bulkhead	54-51-I07a	Aft Engine Mount Bulkhead (GE)	R1 Fitting Fastener Attachment	1	-	-	-	-	-	September 2028
54-51-I07	Strut Aft Engine Mount Bulkhead	54-51-I07b	Aft Engine Mount Bulkhead (GE)	Engine Mount Tension Fitting	1	-	-	-	-	-	September 2028
54-51-I07	Strut Aft Engine Mount Bulkhead	54-51-I07d	Strut Aft Engine Mount Bulkhead (GE)	Cutout Flange	FLS1	-	-	-	January 2022	January 2022	-
54-51-I07	Strut Aft Engine Mount Bulkhead	54-51-I07d	Strut Aft Engine Mount Bulkhead (GE)	Cutout Flange	FLS1	-	-	-	January 2022	January 2022	-
54-51-I07	Strut Aft Engine Mount Bulkhead	54-51-I07d	Strut Aft Engine Mount Bulkhead (GE)	Cutout Flange	1	-	-	-	-	-	September 2028
54-51-I07	Strut Aft Engine Mount Bulkhead	54-51-I07B	Strut Aft Bulkhead (RR)	At Fastener Common to the Aft Upper Spar Fitting WL 148.26 to WL 159.29	1	-	-	54-780-01	-	-	-
54-51-I07	Strut Aft Engine Mount Bulkhead	54-51-I07A,B	Aluminum Aft Strut Bulkhead (RR)	At Fasteners Common to the Aft Upper Spar from WL 148.26 to WL 159.29 and the Two Uppermost Fasteners Common to the R2 Fitting	1	-	54-780-02	-	-	-	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
54-51-I07	Strut Aft Engine Mount Bulkhead	54-51-I07A,B	Aluminum Aft Strut Bulkhead (RR)	At Fastener Common to the Aft Upper Spar from WL 148.26 to WL 159.29 and the Two Uppermost Fasteners Common to the R2 Fitting	1	-	-	54-780-02	-	-	-
54-51-I07	Strut Aft Engine Mount Bulkhead	54-51-I07C	Aluminum Aft Strut Bulkhead (RR)	Forward Upper Flange NSTA 344.00	FLS1	-	54-780-01	-	-	-	-
54-51-I07	Strut Aft Engine Mount Bulkhead	54-51-I07C	Aluminum Aft Strut Bulkhead (RR)	Forward Upper Flange NSTA 344.00	FLS1	-	54-781-02	-	-	-	-
54-51-I07	Strut Aft Engine Mount Bulkhead	54-51-I07C	Aluminum Aft Strut Bulkhead (RR)	Forward Upper Flange NSTA 344.00	1	-	-	54-781-03	-	-	-
54-51-I08	Strut Aft Bulkhead	54-51-I08B	Strut Aft Bulkhead (PW)	At Fastener Common to the Aft Upper Spar Fitting, WL 153.46 to WL 164.99	1	-	-	54-708-01	-	-	-
54-51-I08	Strut Aft Bulkhead	54-51-I08b	Aft Strut Bulkhead (GE)	Aft Bulkhead from NWL 147 to NWL 162	FLS1	-	-	-	-	-	May 2023
54-51-I08	Strut Aft Bulkhead	54-51-I08b	Aft Strut Bulkhead (GE)	Aft Bulkhead from NWL 147 to NWL 162	FLS1	-	-	-	-	-	May 2023
54-51-I08	Strut Aft Bulkhead	54-51-I08d	Aft Strut Bulkhead (GE)	Forward Upper Flange NSTA 325.33	FLS11	-	-	-	January 2022	January 2022	-
54-51-I08	Strut Aft Bulkhead	54-51-I08d	Aft Strut Bulkhead (GE)	Forward Upper Flange NSTA 325.33	FLS1	-	-	-	January 2022	January 2022	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
54-51-I08	Strut Aft Bulkhead	54-51-I08d	Aft Strut Bulkhead (GE)	Forward Upper Flange NSTA 325.33	1	-	-	-	-	-	September 2028
54-51-I09	Forward Engine Mount Assembly	54-51-I09I	PW4090 and PW4098 Forward Engine Mount Assembly (PW)	Forward Mount Thrust Link	1	-	-	54-709-01	-	-	-
55-12-I03	Upper Double Plus Chord	55-12-I03	Upper Double Plus Chord Horizontal Stabilizer	BL 0.0 Skin/Stringer Splice	1	55-701-01	55-701-01	55-701-01	-	-	-
55-12-I03	Upper Double Plus Chord	55-12-I03	Upper Double Plus Chord Horizontal Stabilizer	BL 0.0 Skin/Stringer Splice	1	-	-	-	January 2025	January 2025	-
55-12-I03	Upper Double Plus Chord	55-12-I03	Upper Double Plus Chord Horizontal Stabilizer	BL 0.0 Skin/Stringer Splice	1	-	-	-	-	-	September 2028
55-12-I07	Front Spar Upper Splice Fitting	55-12-I07	Splice Fitting - F/S Upper Chord Horizontal Stabilizer	Inboard Jackscrew Attach Fastener at BL 4.2	1	55-702-01	55-702-01	55-702-01	-	-	-
55-12-I07	Front Spar Upper Splice Fitting	55-12-I07	Splice Fitting - F/S Upper Chord Horizontal Stabilizer	Inboard Jackscrew Attach Fastener at BL 4.2	1	-	-	-	January 2025	January 2025	-
55-12-I07	Front Spar Upper Splice Fitting	55-12-I07	Splice Fitting - F/S Upper Chord Horizontal Stabilizer	Inboard Jackscrew Attach Fastener at BL 4.2	1	-	-	-	-	-	September 20285
55-17-I03	Pivot Fitting, Straps, and Pins	55-17-I03A	Pivot Fitting Lugs	BL +/- 42 and Pivot Hinge Line	1	55-703-01	-	-	-	-	-
55-17-I03	Pivot Fitting, Straps, and Pins	55-17-I03A	Pivot Fitting Lugs	BL +/- 42 and Pivot Hinge Line	1	-	55-703-01	-	-	-	-
55-17-I03	Pivot Fitting, Straps, and Pins	55-17-I03A	Pivot Fitting Lugs	BL +/- 42 and Pivot Hinge Line	1	-	-	55-703-01	-	-	-
55-17-I03	Pivot Fitting, Straps, and Pins	55-17-I03A	Pivot Fitting Lugs	BL +/- 42 and Pivot Hinge Line	1	-	-	-	January 2025	January 2025	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
55-17-I03	Pivot Fitting, Straps, and Pins	55-17-I03A	Pivot Fitting Lugs	BL +/- 42 and Pivot Hinge Line	1	-	-	-	-	-	September 2028
55-17-I03	Pivot Fitting, Straps, and Pins	55-17-I03B	Pivot Fitting Straps (Both Pairs - Upper and Lower)	BL +/- 42, WL 246 and 263, BS 2365	1	55-704-01	-	-	-	-	-
55-17-I03	Pivot Fitting, Straps, and Pins	55-17-I03B	Pivot Fitting Straps (Both Pairs - Upper and Lower)	BL +/- 42, WL 246 and 263, BS 2365	1	55-704-02	-	-	-	-	-
55-17-I03	Pivot Fitting, Straps, and Pins	55-17-I03B	Pivot Fitting Straps (Both Pairs - Upper and Lower)	BL +/- 42, WL 246 and 263, BS 2365	1	55-704-03	55-704-03	55-704-03	January 2025	January 2025	-
55-17-I03	Pivot Fitting, Straps, and Pins	55-17-I03B	Pivot Fitting Straps (Both Pairs - Upper and Lower)	BL +/- 42, WL 246 and 263, BS 2365	1	55-704-04	55-704-04	55-704-04	January 2025	January 2025	-
55-17-I03	Pivot Fitting, Straps, and Pins	55-17-I03B	Pivot Fitting Straps Lower Strap	BL +/- 42, WL 255, BS 2365	1	-	-	-	-	-	September 2028
55-17-I03	Pivot Fitting, Straps, and Pins	55-17-I03C	Pivot Fitting Pins Outer Pin	BL 42 and Pivot Hinge Line	1	55-705-01	-	-	-	-	-
55-17-I03	Pivot Fitting, Straps, and Pins	55-17-I03C	Pivot Fitting Pins Outer Pin	BL 42 and Pivot Hinge Line	1	-	55-705-01	-	-	-	-
55-17-I03	Pivot Fitting, Straps, and Pins	55-17-I03C	Pivot Fitting Pins Outer Pin	BL 42 and Pivot Hinge Line	1	-	-	55-705-01	-	-	-
55-17-I03	Pivot Fitting, Straps, and Pins	55-17-I03C	Pivot Fitting Pins Outer Pin	BL 42 and Pivot Hinge Line	1	-	-	-	January 2025	January 2025	-
55-17-I03	Pivot Fitting, Straps, and Pins	55-17-I03C	Pivot Fitting Pins Outer Pin	BL 42 and Pivot Hinge Line	1	-	-	-	-	-	September 2028
55-18-I01	Jackscrew Fitting	55-18-I01	Jackscrew Fitting, Lugs Dwg. 182W7402	Back-to-Back Lugs BL +/- 5.0 WL 256.32	1	55-706-01	-	-	-	-	-
55-18-I01	Jackscrew Fitting	55-18-I01	Jackscrew Fitting, Lugs Dwg. 182W7402	Back-to-Back Lugs BL +/- 5.0 WL 256.32	1	-	55-706-01	-	-	-	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
55-18-I01	Jackscrew Fitting	55-18-I01	Jackscrew Fitting, Lugs Dwg. 182W7402	Back-to-Back Lugs BL +/- 5.0 WL 256.32	1	-	-	55-706-01	-	-	-
55-18-I01	Jackscrew Fitting	55-18-I01	Jackscrew Fitting, Lugs Dwg. 182W7402	Back-to-Back Lugs BL +/- 5.0 WL 256.32	1	-	-	-	January 2025	January 2025	-
55-18-I01	Jackscrew Fitting	55-18-I01	Jackscrew Fitting, Lugs Dwg. 182W7402	Back-to-Back Lugs BL +/- 5.0 WL 256.32	1	-	-	-	-	-	September 2028
55-27-I03	Actuator Fittings	55-27-I03	Elevator Actuator Fitting 183W1312, L/N 718 and on, and all retrofitted airplanes	Upper Middle Flange	1	55-707-01	55-707-01	55-707-01	January 2025	January 2025	September 2028
57-10-I02	Side of Body Splice, Lower Surface	57-10-I02A	SOB Splice, Lower Surface, T-Chord	INBD and OBD Flanges of T-Chord	1	57-701-02	57-701-02	-	-	-	-
57-10-I02	Side of Body Splice, Lower Surface	57-10-I02A	SOB Splice, Lower Surface, T-Chord	INBD and OBD Flanges of T-Chord	1	-	-	57-701-03	-	-	-
57-10-I02	Side of Body Splice, Lower Surface	57-10-I02A	SOB Splice, Lower Surface, T-Chord	INBD and OBD Flanges of T-Chord	FLS1	-	-	-	January 2022	January 2022	-
57-10-I02	Side of Body Splice, Lower Surface	57-10-I02A	SOB Splice, Lower Surface, T-Chord	INBD and OBD Flanges of T-Chord	FLS1	-	-	-	January 2022	January 2022	-
57-10-I02	Side of Body Splice, Lower Surface	57-10-I02A	Side of Body Splice, Lower Surface	Inboard and outboard flanges of the T-Chord at Stringer L-1	FLS1	-	-	-	-	-	May 2023
57-10-I02	Side of Body Splice, Lower Surface	57-10-I02A	Side of Body Splice, Lower Surface	Inboard and outboard flanges of the T-Chord at Stringer L-1	FLS1	-	-	-	-	-	May 2023



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-10-I02	Side of Body Splice, Lower Surface	57-10-I02B	SOB Splice, Lower Surface, T-Chord	All Fasteners locations not covered by splice plate	1	57-702-02	57-702-02	-	-	-	-
57-10-I02	Side of Body Splice, Lower Surface	57-10-I02B	SOB Splice, Lower Surface, T-Chord	All Fasteners locations not covered by splice plate	1	-	-	57-702-03	-	-	-
57-10-I02	Side of Body Splice, Lower Surface	57-10-I02B	SOB Splice, Lower Surface, T-Chord	All Fasteners locations not covered by splice plate	FLS1	-	-	-	January 2022	January 2022	-
57-10-I02	Side of Body Splice, Lower Surface	57-10-I02B	SOB Splice, Lower Surface, T-Chord	All Fasteners locations not covered by splice plate	FLS1	-	-	-	January 2022	January 2022	-
57-10-I02	Side of Body Splice, Lower Surface	57-10-I02B	Side of Body Splice, Lower Surface	Inspect at all fastener locations not covered by the splice plate	FLS1	-	-	-	-	-	May 2023
57-10-I02	Side of Body Splice, Lower Surface	57-10-I02B	Side of Body Splice, Lower Surface	Inspect at all fastener locations not covered by the splice plate	FLS1	-	-	-	-	-	May 2023
57-10-I02	Side of Body Splice, Lower Surface	57-10-I02C	SOB Splice, Lower Surface, T-Chord	INBD and OBD Flanges of T-chord @ Splice Plate (Str L1,L-10,L14,L-20 and L-23)	1	57-703-02	57-703-02	-	-	-	-
						57-703-03	57-703-03	-	-	-	-
57-10-I02	Side of Body Splice, Lower Surface	57-10-I02C	SOB Splice, Lower Surface, T-Chord	INBD and OBD Flanges of T-chord @ Splice Plate (Str L1,L-10,L14,L-20 and L-23)	1	-	-	57-703-02	-	-	-
						-	-	57-703-03	-	-	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-10-I02	Side of Body Splice, Lower Surface	57-10-I02C	SOB Splice, Lower Surface, T-Chord	INBD and OBD Flanges of T-chord @ Splice Plate (Str L1,L-10,L14,L-20 and L-23)	FLS1	-	-	-	January 2022	January 2022	-
57-10-I02	Side of Body Splice, Lower Surface	57-10-I02C	SOB Splice, Lower Surface, T-Chord	INBD and OBD Flanges of T-chord @ Splice Plate (Str L1,L-10,L14,L-20 and L-23)	FLS1	-	-	-	January 2022	January 2022	-
57-10-I02	Side of Body Splice, Lower Surface	57-10-I02C	Side of Body Splice, Lower Surface	Inboard and Outboard flanges of T-chord at splice plate locations (Str L1,L-10,L14,L-20 and L-23)	FLS1	-	-	-	-	-	May 2023
57-10-I02	Side of Body Splice, Lower Surface	57-10-I02C	Side of Body Splice, Lower Surface	Inboard and Outboard flanges of T-chord at splice plate locations (Str L1,L-10,L14,L-20 and L-23)	FLS1	-	-	-	-	-	May 2023
57-10-I03	Side of Body Splice, Front Spar	57-10-I03A	SOB Splice, Front Spar, Chord	Upper and Lower Front Spar Chords (INBD and OBD of SOB rib)	1	57-704-01	-	-	-	-	-
					FLS1	-	57-704-02	-	-	-	-
57-10-I03	Side of Body Splice, Front Spar	57-10-I03A	SOB Splice, Front Spar, Chord	Upper and Lower Front Spar Chords (INBD and OBD of SOB rib)	FLS1	-	57-704-03	-	-	-	-
57-10-I03	Side of Body Splice, Front Spar	57-10-I03A	SOB Splice, Front Spar, Chord	Upper and Lower Front Spar Chords (INBD and OBD of SOB rib)	1	-	-	57-704-01	-	-	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-10-I03	Side of Body Splice, Front Spar	57-10-I03A	SOB Splice, Front Spar, Chord	Upper and Lower Front Spar Chords (INBD and OBD of SOB rib)	FLS1	-	-	-	January 2022	January 2022	-
57-10-I03	Side of Body Splice, Front Spar	57-10-I03A	SOB Splice, Front Spar, Chord	Upper and Lower Front Spar Chords (INBD and OBD of SOB rib)	FLS1	-	-	-	January 2022	January 2022	-
57-10-I03	Side of Body Splice, Front Spar	57-10-I03A	Side of Body Splice, Front Spar	Chords, Front Spar Lower and Upper Chords (Inboard and Outboard of SOB rib)	FLS1	-	-	-	-	-	May 2023
57-10-I03	Side of Body Splice, Front Spar	57-10-I03A	Side of Body Splice, Front Spar, Chord	Chords, Front Spar Lower and Upper Chords (Inboard and Outboard of SOB rib)	FLS1	-	-	-	-	-	May 2023
57-10-I03	Side of Body Splice, Front Spar	57-10-I03B	Side of Body Splice, Front Spar	Skin, Front Spar Lower and Upper Chords (Inboard and Outboard of SOB rib)	FLS1	-	-	-	-	-	May 2023
57-10-I03	Side of Body Splice, Front Spar	57-10-I03B	Side of Body Splice, Front Spar	Skin, Front Spar Lower and Upper Chords (Inboard and Outboard of .SOB rib)	FLS1	-	-	-	-	-	May 2023
57-10-I04	Side of Body Splice, Rear Spar	57-10-I04A	SOB Splice, Rear Spar, Chord	Upper and Lower Rear Spar Chords (INBD and OBD of SOB rib)	1	57-706-02	-	-	-	-	-
					FLS1	-	57-706-03	-	-	-	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-10-I04	Side of Body Splice, Rear Spar	57-10-I04A	SOB Splice, Rear Spar, Chord	Upper and Lower Rear Spar Chords (INBD and OBD of SOB rib)	FLS1	-	57-706-04	-	-	-	-
57-10-I04	Side of Body Splice, Rear Spar	57-10-I04A	SOB Splice, Rear Spar, Chord	Upper and Lower Rear Spar Chords (INBD and OBD of SOB rib)	1	-	-	57-706-02	-	-	-
57-10-I04	Side of Body Splice, Rear Spar	57-10-I04A	SOB Splice, Rear Spar, Chord	Upper and Lower Rear Spar Chords (INBD and OBD of SOB rib)	FLS1	-	-	-	January 2022	January 2022	-
57-10-I04	Side of Body Splice, Rear Spar	57-10-I04A	SOB Splice, Rear Spar, Chord	Upper and Lower Rear Spar Chords (INBD and OBD of SOB rib)	FLS1	-	-	-	January 2022	January 2022	-
57-10-I04	Side of Body Splice, Rear Spar	57-10-I04A	Side of Body Splice, Rear Spar	Chords, Rear Spar Lower and Upper Chords (Inboard and Outboard of SOB rib)	FLS1	-	-	-	-	-	May 2023
57-10-I04	Side of Body Splice, Rear Spar	57-10-I04A	Side of Body Splice, Rear Spar	Chords, Rear Spar Lower and Upper Chords (Inboard and Outboard of SOB rib)	FLS1	-	-	-	-	-	May 2023
57-10-I04	Side of Body Splice, Rear Spar	57-10-I04B	Side of Body Splice, Rear Spar	Skin, Rear Spar Lower and Upper Chords (Inboard and Outboard of SOB rib)	FLS1	-	-	-	-	-	May 2023
57-10-I04	Side of Body Splice, Rear Spar	57-10-I04B	Side of Body Splice, Rear Spar	Skin, Rear Spar Lower and Upper Chords (Inboard and Outboard of SOB rib)	FLS1	-	-	-	-	-	May 2023



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-12-I02	Front Spar	57-12-I02-1	Body Chord Inspection at Stringer 36 to 41 (Airplanes Without Underwing Longerons Doubler)	Front Spar Bulkhead, Station 1035, Stringer 36 to 41	1	57-708-02	57-708-02	57-708-02	January 2025	January 2025	September 2028
57-12-I02	Front Spar	57-12-I02-1	Body Chord Inspection at Stringer 36 to 41 (Airplanes With Underwing Longerons Doubler)	Front Spar Bulkhead, Station 1035, Stringer 36 to 41	1	57-708-02	57-708-02	57-708-02	January 2025	January 2025	September 2028
57-12-I02	Front Spar	57-12-I02-2	Body Chord Inspection at Splice Plate (Airplanes Without Underwing Longerons Doubler)	Front Spar Bulkhead, Station 1035 Stringer 38 to 39	1	57-708-03	57-708-03	57-708-03	January 2025	January 2025	September 2028
57-12-I02	Front Spar	57-12-I02-2	Body Chord Inspection at Splice Plate (Airplanes With Underwing Longerons Doubler)	Front Spar Bulkhead, Station 1035 Stringer 38 to 39	1	57-708-03	57-708-03	57-708-03	January 2025	January 2025	September 2028
57-15-I01	Lower Panel	57-15-I01A	Wing Center Section (WCS), Lower Panel Typical Stringer	Typical stringer on Lower Panel (WCS from SOB to SOB)	2	57-709-02	57-709-02	-	-	-	-
57-15-I01	Lower Panel	57-15-I01A	Wing Center Section (WCS), Lower Panel Typical Stringer	Typical stringer on Lower Panel (WCS from SOB to SOB)	2	-	-	57-709-03	-	-	-
57-15-I01	Lower Panel	57-15-I01A	Wing Center Section (WCS), Lower Panel Typical Stringer	Typical stringer on Lower Panel (WCS from SOB to SOB)	FLS2	-	-	-	January 2025	January 2025	-
57-15-I01	Lower Panel	57-15-I01A	Wing Center Section (WCS), Lower Panel Typical Stringer	Typical stringer on Lower Panel (WCS from SOB to SOB)	FLS2	-	-	-	January 2025	January 2025	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-15-I01	Lower Panel	57-15-I01A	Wing Center Section - Lower Panel - Typical Stringer	All WCS Lower Panel Typical Stringers from SOB to SOB	FLS2	-	-	-	-	-	May 2028
57-15-I01	Lower Panel	57-15-I01A	Wing Center Section - Lower Panel - Typical Stringer	All WCS Lower Panel Typical Stringers from SOB to SOB	FLS2	-	-	-	-	-	May 2028
57-15-I01	Lower Panel	57-15-I01B	Wing Center Section (WCS), Lower Panel Splice Stringer	Splice stringer on Lower Panel (WCS @ L10,L14, L20 from SOB to SOB)	2	57-709-02	57-709-02	57-710-02	-	-	-
57-15-I01	Lower Panel	57-15-I01B	Wing Center Section (WCS), Lower Panel Splice Stringer	Splice stringer on Lower Panel (WCS @ L10,L14, L20 from SOB to SOB)	FLS2	-	-	-	January 2025	January 2025	-
57-15-I01	Lower Panel	57-15-I01B	Wing Center Section - Lower Panel - Splice Stringer	All WCS Lower Panel Splice Stringers	FLS2	-	-	-	-	-	May 2028
57-15-I01	Lower Panel	57-15-I01B	Wing Center Section - Lower Panel - Splice Stringer	All WCS Lower Panel Splice Stringers	FLS2	-	-	-	January 2025	January 2025	May 2028
57-15-I01	Lower Panel	57-15-I01C	Wing Center Section (WCS), Lower Rear Spar Chord, Lower Chord	Rear Spar Lower Chord (WCS from SOB to SOB)	2	57-711-02	-	-	-	-	-
57-15-I01	Lower Panel	57-15-I01C	Wing Center Section (WCS), Lower Rear Spar Chord, Lower Chord	Rear Spar Lower Chord (WCS from SOB to SOB)	FLS2	-	57-711-06	-	-	-	-
						-	57-711-07	-	-	-	-
						-	57-711-08	-	-	-	-
						-	57-711-12	-	-	-	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-15-I01	Lower Panel	57-15-I01C	Wing Center Section (WCS), Lower Rear Spar Chord, Lower Chord	Rear Spar Lower Chord (WCS from SOB to SOB)	FLS2	-	57-711-09	-	-	-	-
						-	57-711-10	-	-	-	-
57-15-I01	Lower Panel	57-15-I01C	Wing Center Section (WCS), Lower Rear Spar Chord, Lower Chord	Rear Spar Lower Chord (WCS from SOB to SOB)	2	-	-	57-711-03	-	-	-
						-	-	57-711-04	-	-	-
						-	-	57-711-05	-	-	-
						-	-	57-711-11	-	-	-
57-15-I01	Lower Panel	57-15-I01C	Wing Center Section (WCS), Lower Rear Spar Chord, Lower Chord	Rear Spar Lower Chord (WCS from SOB to SOB)	FLS2	-	-	-	January 2025	January 2025	-
57-15-I01	Lower Panel	57-15-I01C	Wing Center Section (WCS), Lower Rear Spar Chord, Lower Chord	Rear Spar Lower Chord (WCS from SOB to SOB)	FLS2	-	-	-	January 2025	January 2025	-
57-15-I01	Lower Panel	57-15-I01C	Wing Center Section - Lower Panel Rear Spar Lower Chord	Chord, WCS Lower Panel Rear Spar Chord from SOB to SOB	FLS2	-	-	-	-	-	May 2028
57-15-I01	Lower Panel	57-15-I01C	Wing Center Section - Lower Panel Rear Spar Lower Chord	Chord, WCS Lower Panel Rear Spar Chord from SOB to SOB	FLS2	-	-	-	-	-	May 2028
57-15-I01	Lower Panel	57-15-I01D	Wing Center Section (WCS), Lower Rear Spar Chord, Lower Skin	Rear Spar Lower Chord (WCS from SOB to SOB)	2	57-712-02	-	-	-	-	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-15-I01	Lower Panel	57-15-I01D	Wing Center Section (WCS), Lower Rear Spar Chord, Lower Skin	Rear Spar Lower Chord (WCS from SOB to SOB)	FLS2	-	57-712-03	-	-	-	-
57-15-I01	Lower Panel	57-15-I01D	Wing Center Section (WCS), Lower Rear Spar Chord, Lower Skin	Rear Spar Lower Chord (WCS from SOB to SOB)	FLS2	-	57-712-04	-	-	-	-
57-15-I01	Lower Panel	57-15-I01D	Wing Center Section (WCS), Lower Rear Spar Chord, Lower Skin	Rear Spar Lower Chord (WCS from SOB to SOB)	2	-	-	57-712-05	-	-	-
						-	-	57-712-06	-	-	-
57-15-I01	Lower Panel	57-15-I01D	Wing Center Section (WCS), Lower Rear Spar Chord, Lower Skin	Rear Spar Lower Chord (WCS from SOB to SOB)	FLS2	-	-	-	January 2025	January 2025	-
57-15-I01	Lower Panel	57-15-I01D	Wing Center Section (WCS), Lower Rear Spar Chord, Lower Skin	Rear Spar Lower Chord (WCS from SOB to SOB)	FLS2	-	-	-	January 2025	January 2025	-
57-15-I01	Lower Panel	57-15-I01D	Wing Center Section - Lower Panel Rear Spar Lower Chord	Skin, WCS Lower Panel Rear Spar Chord from SOB to SOB	FLS2	-	-	-	-	-	May 20285
57-15-I01	Lower Panel	57-15-I01D	Wing Center Section - Lower Panel Rear Spar Lower Chord	Skin, WCS Lower Panel Rear Spar Chord from SOB to SOB	FLS2	-	-	-	-	-	May 2028
57-15-I01	Lower Panel	57-15-I01E	Wing Center Section (WCS), Lower Panel Keel Beam Chord, Lower Skin	Lower Skin at Rear Spar Chord/Keel Attachment (LBL 15 to RBL 15)	1	57-713-02	-	-	-	-	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-15-I01	Lower Panel	57-15-I01E	Wing Center Section (WCS), Lower Panel Keel Beam Chord, Lower Skin	Lower Skin at Rear Spar Chord/Keel Attachment (LBL 15 to RBL 15)	FLS1	-	57-713-03	-	-	-	-
57-15-I01	Lower Panel	57-15-I01E	Wing Center Section (WCS), Lower Panel Keel Beam Chord, Lower Skin	Lower Skin at Rear Spar Chord/Keel Attachment (LBL 15 to RBL 15)	FLS1	-	57-713-04	-	-	-	-
57-15-I01	Lower Panel	57-15-I01E	Wing Center Section (WCS), Lower Panel Keel Beam Chord, Lower Skin	Lower Skin at Rear Spar Chord/Keel Attachment (LBL 15 to RBL 15)	1	-	-	57-713-05	-	-	-
57-15-I01	Lower Panel	57-15-I01E	Wing Center Section (WCS), Lower Panel Keel Beam Chord, Lower Skin	Lower Skin at Rear Spar Chord/Keel Attachment (LBL 15 to RBL 15)	FLS1	-	-	-	January 2022	January 2022	-
57-15-I01	Lower Panel	57-15-I01E	Wing Center Section (WCS), Lower Panel Keel Beam Chord, Lower Skin	Lower Skin at Rear Spar Chord/Keel Attachment (LBL 15 to RBL 15)	FLS1	-	-	-	January 2022	January 2022	-
57-15-I01	Lower Panel	57-15-I01E	Wing Center Section Lower Panel - Keel Beam Chord Attachment	Skin, WCS Lower Panel Keel Beam Chord Attachment at the Rear Spar Chord	FLS1	-	-	-	-	-	May 2023
57-15-I01	Lower Panel	57-15-I01E	Wing Center Section Lower Panel - Keel Beam Chord Attachment	Skin, WCS Lower Panel Keel Beam Chord Attachment at the Rear Spar Chord	FLS1	-	-	-	-	-	May 2023
57-15-I01	Lower Panel	57-15-I01F	Wing Center Section (WCS), Lower Panel Keel Beam Chord, Lower Chord	Rear Spar Chord at Keel Attachment (LBL 15 to RBL 15)	2	57-714-02	57-714-02	-	-	-	-
						57-714-03	57-714-03	-	-	-	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-15-I01	Lower Panel	57-15-I01F	Wing Center Section, Lower Panel - Keel Beam Chord, Lower Chord	Rear Spar Chord at Keel Attachment (LBL 15 to RBL 15)	2	-	-	57-714-02	-	-	-
						-	-	57-714-03	-	-	-
57-15-I01	Lower Panel	57-15-I01F	Wing Center Section, Lower Panel - Keel Beam Chord, Lower Chord	Rear Spar Chord at Keel Attachment (LBL 15 to RBL 15)	2	-	-	-	May 2028	May 2028	-
57-15-I01	Lower Panel	57-15-I01F	Wing Center Section Lower Panel - Keel Beam Chord Attachment	Chord, WCS Lower Panel Keel Beam Chord Attachment at the Rear Spar Chord	FLS2	-	-	-	-	-	May 2028
57-15-I01	Lower Panel	57-15-I01F	Wing Center Section Lower Panel - Keel Beam Chord Attachment	Chord, WCS Lower Panel Keel Beam Chord Attachment at the Rear Spar Chord	FLS2	-	-	-	-	-	May 2028
57-15-I01	Lower Panel	57-15-I01G	Wing Center Section (WCS) Lower Front Spar Chord Lower Chord	Front Spar Lower Chord (WCS from BL 67 to BL 103)	2	53-888-00	53-888-00	53-888-00	May 2028	May 2028	-
						53-890-00	53-890-00	53-890-00	May 2028	May 2028	-
57-20-I01	Lower Panel	57-20-I01A	Wing Outboard, Typical Rear Spar Attachment, Lower Chord	Rear Spar Attachment from SOB to Rib 12 (Mid Rib)	2	57-706-02	-	-	-	-	-
					FLS2	-	57-716-04	-	-	-	-
57-20-I01	Lower Panel	57-20-I01A	Wing Outboard, Typical Rear Spar Attachment, Lower Chord	Rear Spar Attachment from SOB to Rib 12 (Mid Rib)	FLS2	-	57-716-05	-	-	-	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-20-I01	Lower Panel	57-20-I01A	Wing Outboard, Typical Rear Spar Attachment, Lower Chord	Rear Spar Attachment from SOB to Rib 12 (Mid Rib)	2	-	-	57-706-02	-	-	-
						-	-	57-716-03	-	-	-
57-20-I01	Lower Panel	57-20-I01A	Wing Outboard, Typical Rear Spar Attachment, Lower Chord	Rear Spar Attachment from SOB to Rib 15 (Mid Rib)	FLS2	-	-	-	January 2025	January 2025	-
57-20-I01	Lower Panel	57-20-I01A	Wing Outboard, Typical Rear Spar Attachment, Lower Chord	Rear Spar Attachment from SOB to Rib 15 (Mid Rib)	FLS2	-	-	-	January 2025	January 2025	-
57-20-I01	Lower Panel	57-20-I01A	Wing Outboard - Lower Panel Rear Spar Lower Chord	Chord, O/B Wing Lower Panel Rear Spar Chord from SOB to Rib 15 except at Ribpost locations	FLS2	-	-	-	-	-	May 2028
57-20-I01	Lower Panel	57-20-I01A	Wing Outboard - Lower Panel Rear Spar Lower Chord	Chord, O/B Wing Lower Panel Rear Spar Chord from SOB to Rib 15 except at Ribpost locations	FLS2	-	-	-	-	-	May 2028
57-20-I01	Lower Panel	57-20-I01B	Wing Outboard, Typical Rear Spar Attachment, Lower Chord	Rear Spar Chord Attachment from Rib 15 to Wingtip (Mid Rib)	FLS2	-	-	-	January 2025	January 2025	-
57-20-I01	Lower Panel	57-20-I01B	Wing Outboard, Typical Rear Spar Attachment, Lower Chord	Rear Spar Chord Attachment from Rib 15 to Wingtip (Mid Rib)	FLS2	-	-	-	January 2025	January 2025	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-20-I01	Lower Panel	57-20-I01B	Wing Outboard - Lower Panel Rear Spar Lower Chord	Chord, O/B Wing Lower Panel Rear Spar Chord from SOB to Rib 15 except at Ribpost locations	FLS2	-	-	-	-	-	May 2028
57-20-I01	Lower Panel	57-20-I01B	Wing Outboard - Lower Panel Rear Spar Lower Chord	Chord, O/B Wing Lower Panel Rear Spar Chord from SOB to Rib 15 except at Ribpost locations	FLS2	-	-	-	-	-	May 2028
57-20-I01	Lower Panel	57-20-I01C	Wing Outboard, Typical Rear Spar Attachment, Lower Skin	Rear Spar Chord Attachment at Trailing Edge fairing locations	FLS2	-	-	-	January 2025	January 2025	-
57-20-I01	Lower Panel	57-20-I01C	Wing Outboard, Typical Rear Spar Attachment, Lower Skin	Rear Spar Chord Attachment at Trailing Edge fairing locations	FLS2	-	-	-	January 2025	January 2025	-
57-20-I01	Lower Panel	57-20-I01C	Wing Outboard - Lower Panel Rear Spar Lower Chord	Skin, O/B Wing Lower Panel Rear Spar Chord at the trailing edge fairing locations	FLS2	-	-	-	-	-	May 2028
57-20-I01	Lower Panel	57-20-I01C	Wing Outboard - Lower Panel Rear Spar Lower Chord	Skin, O/B Wing Lower Panel Rear Spar Chord at the trailing edge fairing locations	FLS2	-	-	-	-	-	May 2028
57-20-I01	Lower Panel	57-20-I01D	Wing Outboard, Typical Splice Stringer	Stringer L10-L14 from SOB to Rib 36, L20 From Rib 8 to Rib 18	2	57-719-02	-	-	-	-	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-20-I01	Lower Panel	57-20-I01D	Wing Outboard, Typical Splice Stringer	Stringer L10-L14 from SOB to Rib 36, L20 From Rib 8 to Rib 18	FLS2	-	57-719-03	-	-	-	-
57-20-I01	Lower Panel	57-20-I01D	Wing Outboard, Typical Splice Stringer	Stringer L10-L14 from SOB to Rib 36, L20 From Rib 8 to Rib 18	FLS2	-	57-719-04	-	-	-	-
57-20-I01	Lower Panel	57-20-I01D	Wing Outboard, Typical Splice Stringer	Stringer L10-L14 from SOB to Rib 36, L20 From Rib 8 to Rib 18	2	-	-	57-719-02	-	-	-
57-20-I01	Lower Panel	57-20-I01E	Wing Outboard, Typical Splice Stringer	Stringer L10-L14 at Nacelle Fitting and Dry Bay Locations	FLS2	-	-	-	January 2025	January 2025	-
57-20-I01	Lower Panel	57-20-I01E	Wing Outboard, Typical Splice Stringer	Stringer L10-L14 at Nacelle Fitting and Dry Bay Locations	FLS2	-	-	-	January 2025	January 2025	-
57-20-I01	Lower Panel	57-20-I01E	Outboard Wing - Lower Panel Splice Stringer	O/B Wing Lower Splice Stringers at the nacelle fairing and dry bay locations	FLS2	-	-	-	-	-	May 2028
57-20-I01	Lower Panel	57-20-I01E	Outboard Wing - Lower Panel Splice Stringer	O/B Wing Lower Splice Stringers at the nacelle fairing and dry bay locations	FLS2	-	-	-	-	-	May 2028
57-20-I01	Lower Panel	57-20-I01F	Wing Outboard, Typical Splice Stringer	Stringer L10-L14 at Nacelle Fitting, and L10 at Rib 30, 21 and 12	2	57-721-01	-	-	-	-	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-20-I01	Lower Panel	57-20-I01F	Wing Outboard, Typical Splice Stringer	Stringer L10 - L14 at Nacelle Fitting, and L10 at Rib 30, 21 and 12	FLS2	-	57-721-02	-	-	-	-
57-20-I01	Lower Panel	57-20-I01F	Wing Outboard, Typical Splice Stringer	Stringer L10 - L14 at Nacelle Fitting, and L10 at Rib 30, 21 and 12	FLS2	-	57-721-03	-	-	-	-
57-20-I01	Lower Panel	57-20-I01G	Wing Outboard, Lower Panel Rear Spar Chord, Lower Chord	Rear Spar Chord Attachment from SOB to Rib 12 at Rib Post	1	57-722-01	-	-	-	-	-
						57-722-02	-	-	-	-	-
					FLS1	-	57-722-03	-	-	-	-
						-	57-722-04	-	-	-	-
57-20-I01	Lower Panel	57-20-I01G	Wing Outboard, Lower Panel Rear Spar Chord, Lower Chord	Rear Spar Chord Attachment from SOB to Rib 12 at Rib Post	FLS1	-	57-722-05	-	-	-	-
						-	57-722-06	-	-	-	-
57-20-I01	Lower Panel	57-20-I01G	Wing Outboard, Lower Panel Rear Spar Chord, Lower Chord	Rear Spar Chord Attachment from SOB to Rib 12 at Rib Post	1	-	-	57-722-02	-	-	-
						-	-	57-722-07	-	-	-
57-20-I01	Lower Panel	57-20-I01G	Wing Outboard, Lower Panel Rear Spar Chord, Lower Chord	Rear Spar Chord Attachment from SOB to Rib 15 at Rib Post	FLS1	-	-	-	January 2022	January 2022	-
57-20-I01	Lower Panel	57-20-I01G	Wing Outboard, Lower Panel Rear Spar Chord, Lower Chord	Rear Spar Chord Attachment from SOB to Rib 15 at Rib Post	FLS1	-	-	-	January 2022	January 2022	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-20-I01	Lower Panel	57-20-I01G	Wing Outboard, Lower Panel Rear Spar Lower Chord	O/B Wing Lower Panel Rear Spar Chord from Rib 15 to wingtip at all ribpost locations	FLS1	-	-	-	-	-	May 2023
57-20-I01	Lower Panel	57-20-I01G	Wing Outboard, Lower Panel Rear Spar Lower Chord	O/B Wing Lower Panel Rear Spar Chord from Rib 15 to wingtip at all ribpost locations	FLS1	-	-	-	-	-	May 2023
57-20-I01	Lower Panel	57-20-I01H	Wing Outboard, Lower Panel Rear Spar Chord, Lower Chord	Skin and Rear Spar Web Attachment from Rib 15 to Wingtip at Rib Post	FLS1	-	-	-	January 2022	January 2022	-
57-20-I01	Lower Panel	57-20-I01H	Wing Outboard, Lower Panel Rear Spar Chord, Lower Chord	Skin and Rear Spar Web Attachment from Rib 15 to Wingtip at Rib Post	FLS1	-	-	-	January 2022	January 2022	-
57-20-I01	Lower Panel	57-20-I01H	Wing Outboard, Lower Panel Front Spar Lower Chord	O/B Wing Lower Panel Front Spar Chord from Rib 15 to wingtip at all ribpost locations	FLS1	-	-	-	-	-	May 2023
57-20-I01	Lower Panel	57-20-I01H	Wing Outboard, Lower Panel Front Spar Lower Chord	O/B Wing Lower Panel Front Spar Chord from Rib 15 to wingtip at all ribpost locations	FLS1	-	-	-	-	-	May 2023
57-20-I01	Lower Panel	57-20-I01J	Wing Outboard, Lower Panel Front Spar Chord, Lower Chord	Skin to F/Spar Chord Attachment at Nacelle Fitting	1	57-724-02	57-724-02	-	-	-	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-20-I01	Lower Panel	57-20-I01J	Wing Outboard, Lower Panel Front Spar Chord, Lower Chord	Skin to F/Spar Chord Attachment at Nacelle Fitting	1	-	-	57-724-02	-	-	-
57-20-I01	Lower Panel	57-20-I01J	Wing Outboard, Lower Panel Front Spar Chord, Lower Chord	Skin to F/Spar Chord Attachment at Nacelle Fitting	FLS1	-	-	-	January 2022	January 2022	-
57-20-I01	Lower Panel	57-20-I01J	Wing Outboard, Lower Panel Front Spar Chord, Lower Chord	Skin to F/Spar Chord Attachment at Nacelle Fitting	FLS1	-	-	-	January 2022	January 2022	-
57-20-I01	Lower Panel	57-20-I01J	Wing Outboard, Lower Panel Front Spar Lower Chord	Chord, O/B Wing Lower Panel Front Spar Chord at the nacelle fitting attachment locations	FLS1	-	-	-	-	-	May 2023
57-20-I01	Lower Panel	57-20-I01J	Wing Outboard, Lower Panel Front Spar Lower Chord	Chord, O/B Wing Lower Panel Front Spar Chord at the nacelle fitting attachment locations	FLS1	-	-	-	-	-	May 2023
57-20-I01	Lower Panel	57-20-I01K	Wing Outboard, Lower Panel Front Spar Chord, Lower Skin	Skin to F/Spar Chord Attachment at Nacelle Fitting	FLS1	-	-	-	January 2022	January 2022	-
57-20-I01	Lower Panel	57-20-I01K	Wing Outboard, Lower Panel Front Spar Chord, Lower Skin	Skin to F/Spar Chord Attachment at Nacelle Fitting	FLS1	-	-	-	January 2022	January 2022	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-20-I01	Lower Panel	57-20-I01K	Wing Outboard, Lower Panel Front Spar Lower Chord	Skin, O/B Wing Lower Panel Front Spar Chord at the nacelle fitting attachment locations	FLS1	-	-	-	-	-	May 2023
57-20-I01	Lower Panel	57-20-I01K	Wing Outboard, Lower Panel Front Spar Lower Chord	Skin, O/B Wing Lower Panel Front Spar Chord at the nacelle fitting attachment locations	FLS1	-	-	-	-	-	May 2023
57-20-I01	Lower Panel	57-20-I01L1	Wing Outboard, Lower Panel Front Spar Chord, Lower Chord	Skin to F/Spar Chord Attachment from SOB to Wingtip except between Rib 30 to 44 and at Nacelle Fitting and Rib Post	FLS2	-	-	-	January 2025	January 2025	-
57-20-I01	Lower Panel	57-20-I01L2	Wing Outboard, Lower Panel Front Spar Chord, Lower Chord	Skin to F/Spar Chord Attachment from Rib 30 to Rib 44, except at Rib Post	FLS2	-	-	-	January 2025	January 2025	-
57-20-I01	Lower Panel	57-20-I01L	Wing Outboard, Lower Panel Front Spar Chord, Lower Chord	Skin to F/Spar Chord Attachment from SOB to Wingtip except at Nacelle Fitting Attachment and Rib Post	FLS2	-	-	-	January 2025	January 2025	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-20-I01	Lower Panel	57-20-I01L	Wing Outboard, Lower Panel Front Spar Lower Chord	Chord, O/B Wing Lower Panel Front Spar Chord from SOB to Wingtip except at ribpost locations	FLS2	-	-	-	-	-	May 2028
57-20-I01	Lower Panel	57-20-I01L	Wing Outboard, Lower Panel Front Spar Lower Chord	Chord, O/B Wing Lower Panel Front Spar Chord from SOB to Wingtip except at ribpost locations	FLS2	-	-	-	-	-	May 2028
57-20-I01	Lower Panel	57-20-I01M	Wing Outboard, Lower Panel Front Spar Chord, Lower Chord	Skin to F/Spar Chord Attachment from SOB to Wingtip at all Rib Post	FLS1	-	-	-	January 2022	January 2022	-
57-20-I01	Lower Panel	57-20-I01M	Wing Outboard, Lower Panel Front Spar Chord, Lower Chord	Skin to F/Spar Chord Attachment from SOB to Wingtip at all Rib Post	FLS1	-	-	-	January 2022	January 2022	-
57-20-I01	Lower Panel	57-20-I01M	Wing Outboard, Lower Panel Front Spar Lower Chord	Chord, O/B Wing Lower Panel Front Spar Chord from SOB to Wingtip at all ribpost locations	FLS11	-	-	-	-	-	May 2023
57-20-I01	Lower Panel	57-20-I01M	Wing Outboard, Lower Panel Front Spar Lower Chord	Chord, O/B Wing Lower Panel Front Spar Chord from SOB to Wingtip at all ribpost locations	FLS1	-	-	-	-	-	May 2023
57-20-I01	Lower Panel	57-20-I01N	Wing Outboard, MLG Beam Support Fitting, Mid Rib, Lower Skin	Wing Skin Tab-Out btwn Ribs 11 and 12 at MLG Beam Support Fitting	2	57-728-02	57-728-02	-	-	-	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-20-I01	Lower Panel	57-20-I01N	Wing Outboard, MLG Beam Support Fitting, Mid Rib, Lower Skin	Wing Skin Tab-Out btwn Ribs 11 and 12 at MLG Beam Support Fitting	2	-	-	57-728-02	-	-	-
57-20-I01	Lower Panel	57-20-I01N	Wing Outboard, MLG Beam Support Fitting, Mid Rib, Lower Skin	Wing Skin Tab-Out btwn Ribs 11 and 12 at MLG Beam Support Fitting	FLS2	-	-	-	January 2025	January 2025	-
57-20-I01	Lower Panel	57-20-I01N	Wing Outboard, MLG Beam Support Fitting, Mid Rib, Lower Skin	Wing Skin Tab-Out btwn Ribs 11 and 12 at MLG Beam Support Fitting	FLS2	-	-	-	January 2025	January 2025	-
57-20-I01	Lower Panel	57-20-I01N	Lower Panel - MLG Beam Outboard Support Fitting Attachment	All fastener locations common to the O/B Wing Lower Panel Skin tab and the MLG Beam Outboard Support Fitting	FLS2	-	-	-	-	-	May 2028
57-20-I01	Lower Panel	57-20-I01N	Lower Panel - MLG Beam Outboard Support Fitting Attachment	All fastener locations common to the O/B Wing Lower Panel Skin tab and the MLG Beam Outboard Support Fitting	FLS2	-	-	-	-	-	May 2028
57-20-I01	Lower Panel	57-20-I01P	Wing Outboard, Typical Stringer Attachment at Nacelle FTG	Typical stringers at Nacelle Fitting locations	2	57-729-01	-	-	-	-	-
						57-729-02	-	-	-	-	-
					FLS2	-	57-729-03	-	-	-	-
						-	57-729-04	-	-	-	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-20-I01	Lower Panel	57-20-I01P	Wing Outboard, Typical Stringer Attachment at Nacelle FTG	Typical stringers at Nacelle Fitting locations	FLS2	-	57-729-05	-	-	-	-
57-20-I01	Lower Panel	57-20-I01P	Wing Outboard, Typical Stringer Attachment at Nacelle FTG	Typical stringers at Nacelle Fitting locations	2	-	-	57-729-01	-	-	-
						-	-	57-729-06	-	-	-
57-20-I01	Lower Panel	57-20-I01P	Wing Outboard, Typical Stringer Attachment at Nacelle FTG	Typical stringers at Nacelle Fitting locations	FLS2	-	-	-	January 2025	January 2025	-
57-20-I01	Lower Panel	57-20-I01P	Wing Outboard, Typical Stringer Attachment at Nacelle FTG	Typical stringers at Nacelle Fitting locations	FLS2	-	-	-	January 2025	January 2025	-
57-20-I01	Lower Panel	57-20-I01P	Outboard Wing - Lower Panel Typical Skin-Stringer Attachment	O/B Wing Lower Panel Typical Stringers at Nacelle Fairing Location	FLS2	-	-	-	-	-	May 2028
57-20-I01	Lower Panel	57-20-I01P	Outboard Wing - Lower Panel Typical Skin-Stringer Attachment	O/B Wing Lower Panel Typical Stringers at Nacelle Fairing Location	FLS2	-	-	-	-	-	May 2028
57-20-I01	Lower Panel	57-20-I01Q	Wing Outboard, Typical Rail Stringer at Access Door	Typical Rail Stringers at Access door from SOB to Wingtip except at Nacelle Fairing	2	-	-	57-730-01	-	-	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-20-I01	Lower Panel	57-20-I01Q	Wing Outboard, Typical Rail Stringer at Access Door	Typical Rail Stringers at Access door from SOB to Wingtip except at Nacelle Fairing	FLS2	-	-	-	January 2025	January 2025	-
57-20-I01	Lower Panel	57-20-I01Q	Outboard Wing - Lower Panel Typical Attachment at Access Door/Hole	Stringer, O/B Wing Lower Panel Rail Stringer from SOB to Wingtip except at the nacelle fairing	FLS2	-	-	-	-	-	May 2028
57-20-I01	Lower Panel	57-20-I01Q	Outboard Wing - Lower Panel Typical Attachment at Access Door/Hole	Stringer, O/B Wing Lower Panel Rail Stringer from SOB to Wingtip except at the nacelle fairing	FLS2	-	-	-	-	-	May 2028
57-20-I01	Lower Panel	57-20-I01R	Wing Outboard, Typical Rail Stringer at Access Door	Typical Rail Stringers at Access door at Nacelle Fairing	FLS2	-	-	-	January 2025	January 2025	-
57-20-I01	Lower Panel	57-20-I01R	Wing Outboard, Typical Rail Stringer at Access Door	Typical Rail Stringers at Access door at Nacelle Fairing	FLS2	-	-	-	January 2025	January 2025	-
57-20-I01	Lower Panel	57-20-I01R	Outboard Wing - Lower Panel Typical Attachment at Access Door/Hole	Stringer, O/B Wing Lower Panel Rail Stringer at the Nacelle Fairing	FLS2	-	-	-	-	-	May 2028
57-20-I01	Lower Panel	57-20-I01R	Outboard Wing - Lower Panel Typical Attachment at Access Door/Hole	Stringer, O/B Wing Lower Panel Rail Stringer at the Nacelle Fairing	FLS2	-	-	-	-	-	May 2028



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-20-I01	Lower Panel	57-20-I01S	Outboard Wing - Lower Panel Splice at Rib 46	Fastener locations (inboard and outboard of Rib 46) common to the Lower Rib Chord and Lower Rear Spar Chord	FLS2	-	-	-	January 2025	January 2025	May 2028
					FLS2	-	-	-	January 2025	January 2025	May 2028
57-20-I01	Lower Panel	57-20-I01S	Outboard Wing - Lower Panel Splice at Rib 46	Fastener locations (inboard and outboard of Rib 46) common to the Lower Rib Chord and Lower Rear Spar Chord	FLS2	-	-	-	January 2025	January 2025	May 2028
					FLS2	-	-	-	January 2025	January 2025	-May 2028
57-20-I01	Lower Panel	57-20-I01T	Outboard Wing - Lower Panel Splice at Rib 46	Fastener locations (inboard and outboard of Rib 46) common to the Lower Rib Chord and Paddle Fittings	FLS1	-	-	-	January 2022	January 2022	May 2023
					FLS1	-	-	-	January 2022	January 2022	May 2023
57-20-I01	Lower Panel	57-20-I01T	Outboard Wing - Lower Panel Splice at Rib 46	Fastener locations (inboard and outboard of Rib 46) common to the Lower Rib Chord and Paddle Fittings	FLS1	-	-	-	January 2022	January 2022	May 2023
					FLS1	-	-	-	January 2022	January 2022	May 2023
57-20-I02	Upper Panel	57-20-I02A	Wing Outboard, Upper Panel, MLG Beam Support Fitting, Upper Skin	Fastener locations C/T Upper Panel Skin Tab and MLG Beam SPRT FTG	2	57-734-01	57-734-01	57-734-01	-	-	-
57-20-I02	Upper Panel	57-20-I02A	Wing Outboard, Upper Panel, MLG Beam Support Fitting, Upper Skin	Fastener locations C/T Upper Panel Skin Tab and MLG Beam SPRT FTG	2	-	-	-	May 2028	May 2028	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-20-I02	Upper Panel	57-20-I02A	Upper Panel - MLG Beam Outboard Support Fitting Attachment	Fastener locations common to the O/B Wing Upper panel Skin Tab and the MLG Beam Outboard Support Fitting	FLS2	-	-	-	-	-	May 2028
57-20-I02	Upper Panel	57-20-I02A	Upper Panel - MLG Beam Outboard Support Fitting Attachment	Fastener locations common to the O/B Wing Upper panel Skin Tab and the MLG Beam Outboard Support Fitting	FLS2	-	-	-	-	-	May 2028
57-20-I02	Upper Panel	57-20-I02B	Wing Outboard, Upper Panel, Front Spar Upper Chord	F/Spar Upper Chord from Rib 8 to Rib 11 (MidRib)	2	57-735-01	-	57-735-01	-	-	-
					FLS2	-	57-735-03	-	-	-	-
57-20-I02	Upper Panel	57-20-I02B	Wing Outboard, Upper Panel, Front Spar Upper Chord	F/Spar Upper chords from SOB to Wingtip (MidRib)	FLS2	-	57-735-04	-	-	-	-
57-20-I02	Upper Panel	57-20-I02B	Wing Outboard, Upper Panel, Front Spar Upper Chord	F/Spar Upper Chord from Rib 7 to Rib 11 (MidRib)	FLS2	-	-	-	January 2025	January 2025	-
					FLS2	-	-	-	January 2025	January 2025	-
57-20-I02	Upper Panel	57-20-I02B	Wing Outboard, Upper Panel, Front Spar Upper Chord	F/Spar Upper chords from SOB to Wingtip at Mid Rib except at F/Spar Splice between Rib 43 and Rib 44	FLS2	-	-	-	January 2025	January 2025	-
					FLS2	-	-	-	January 2025	January 2025	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-20-102	Upper Panel	57-20-102B	Wing Outboard - Upper Panel, Front Spar Upper Chord	O/B Wing Upper Panel Front Spar Chord from SOB to Wingtip except at Ribpost locations	FLS2	-	-	-	-	-	May 2028
					FLS2	-	-	-	-	-	May 2028
57-20-102	Upper Panel	57-20-102C	Wing Outboard, Upper Panel, Front Spar Upper Chord	Front Spar Upper chords from SOB to Wingtip at Rib Post Location	FLS1	-	-	-	January 2022	January 2022	-
					FLS1	-	-	-	January 2022	January 2022	-
57-20-102	Upper Panel	57-20-102C	Wing Outboard, Upper Panel, Front Spar Upper Chord	Front Spar Upper chords from SOB to Wingtip at Rib Post Location	FLS1	-	-	-	January 2022	January 2022	-
					FLS1	-	-	-	January 2022	January 2022	-
57-20-102	Upper Panel	57-20-102C	Wing Outboard, Upper Panel, Front Spar Upper Chord	O/B Wing Upper Panel Front Spar Chord from SOB to Wingtip at all Ribpost Locations	FLS1	-	-	-	-	-	May 2023
57-20-102	Upper Panel	57-20-102C	Wing Outboard, Upper Panel, Front Spar Upper Chord	O/B Wing Upper Panel Front Spar Chord from SOB to Wingtip at all Ribpost Locations	FLS1	-	-	-	-	-	May 2023
57-20-102	Upper Panel	57-20-102D	Wing Outboard, Upper Panel, Rear Spar Upper Chord	Rear Spar Upper Chord from SOB to Wingtip at Rib Post Location	1	57-737-01	-	-	-	-	-
57-20-102	Upper Panel	57-20-102D	Wing Outboard, Upper Panel, Rear Spar Upper Chord	Rear Spar Upper Chord from SOB to Wingtip at Rib Post Location	FLS1	-	57-737-03	-	-	-	-
57-20-102	Upper Panel	57-20-102D	Wing Outboard, Upper Panel, Rear Spar Upper Chord	Rear Spar Upper Chord from SOB to Wingtip at Rib Post Location	FLS1	-	57-737-04	-	-	-	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-20-I02	Upper Panel	57-20-I02D	Wing Outboard, Upper Panel, Rear Spar Upper Chord	Rear Spar Upper Chord from SOB to Wingtip at Rib Post Location	1	-	-	57-737-05	-	-	-
						-	-	57-737-06	-	-	-
57-20-I02	Upper Panel	57-20-I02D	Wing Outboard, Upper Panel, Rear Spar Upper Chord	Rear Spar Upper Chord from SOB to Wingtip at Rib Post Location	FLS1	-	-	-	January 2022	January 2022	-
					FLS1	-	-	-	January 2022	January 2022	-
57-20-I02	Upper Panel	57-20-I02D	Wing Outboard, Upper Panel, Rear Spar Upper Chord	Rear Spar Upper Chord from SOB to Wingtip at Rib Post Location	FLS1	-	-	-	January 2022	January 2022	-
					FLS1	-	-	-	January 2022	January 2022	-
57-20-I02	Upper Panel	57-20-I02D	Wing Outboard, Upper Panel, Rear Spar Upper Chord	O/B Wing Upper Panel Rear Spar Chord from SOB to Wingtip at all Ribpost Locations	FLS1	-	-	-	-	-	May 2023
57-20-I02	Upper Panel	57-20-I02D	Wing Outboard, Upper Panel, Rear Spar Upper Chord	O/B Wing Upper Panel Rear Spar Chord from SOB to Wingtip at all Ribpost Locations	FLS1	-	-	-	-	-	May 2023
57-20-I02	Upper Panel	57-20-I02E	Wing Outboard, Upper Panel, Rear Spar Upper Chord	Rear Spar Upper Chord from Rib 8 to Rib 12 only	FLS2	-	-	-	January 2025	January 2025	-
57-20-I02	Upper Panel	57-20-I02E	Wing Outboard, Upper Panel, Rear Spar Upper Chord	O/B Wing Upper Panel Rear Spar Chord from Rib 8 to Rib 12 only	FLS2	-	-	-	-	-	May 2028
57-20-I02	Upper Panel	57-20-I02E	Wing Outboard, Upper Panel, Rear Spar Upper Chord	O/B Wing Upper Panel Rear Spar Chord from Rib 8 to Rib 12 only	FLS2	-	-	-	-	-	May 2028



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-20-I02	Upper Panel	57-20-I02F	Wing Outboard, Upper Panel, Rear Spar Upper Chord	Rear Spar Upper Chord from Rib 8 to Rib 11 (Mid Rib)	2	57-739-01	-	57-739-01	-	-	-
					FLS2	-	57-739-03	-	-	-	-
57-20-I02	Upper Panel	57-20-I02F	Wing Outboard, Upper Panel, Rear Spar Upper Chord	Rear Spar Upper Chord from SOB to Wingtip (Mid Rib)	FLS2	-	57-739-04	-	-	-	-
57-20-I02	Upper Panel	57-20-I02F	Wing Outboard, Upper Panel, Rear Spar Upper Chord	Rear Spar Upper Chord from Rib 7 to Rib 11 (Mid Rib)	FLS2	-	-	-	January 2025	January 2025	-
					FLS2	-	-	-	January 2025	January 2025	-
57-20-I02	Upper Panel	57-20-I02F	Wing Outboard, Upper Panel, Rear Spar Upper Chord	Rear Spar Upper Chord from SOB to Wingtip (Mid Rib)	FLS2	-	-	-	January 2025	January 2025	-
57-20-I02	Upper Panel	57-20-I02F	Wing Outboard, Upper Panel, Rear Spar Upper Chord	O/B Wing Upper Panel Rear Spar Chord from SOB to Wingtip except at Ribpost	FLS2	-	-	-	-	-	May 2028
57-20-I02	Upper Panel	57-20-I02F	Wing Outboard, Upper Panel, Rear Spar Upper Chord	O/B Wing Upper Panel Rear Spar Chord from SOB to wingtip except at Ribpost	FLS2	-	-	-	-	-	May 2028
57-20-I02	Upper Panel	57-20-I02G	Wing Outboard, Upper Skin Tab	Upper Skin Tab at fastener locations C/T Skin and R1 Fitting	2	57-740-01	57-740-01	57-740-01	-	-	-
57-20-I02	Upper Panel	57-20-I02H	Wing Outboard, Upper Skin Nacelle Attachment Tab	Upper Skin Tab at fastener locations C/T Skin and F/Spar Chord	2	-	-	-	May 2028	May 2028	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-20-I02	Upper Panel	57-20-I02H	Upper Panel - Nacelle Attachment Tab	Fastener locations common to the O/B Wing Upper Panel Skin and Front Spar Upper Chord	FLS2	-	-	-	-	-	May 2028
57-20-I02	Upper Panel	57-20-I02H	Upper Panel - Nacelle Attachment Tab	Fastener locations common to the O/B Wing Upper Panel Skin and Front Spar Upper Chord	FLS2	-	-	-	-	-	May 2028
57-20-I02	Upper Panel	57-20-I02J	Wing Outboard, Upper Panel, Typical Splice Stringer	Upper Panel Splice Stringers @ U-10, U24 from Rib 3 to Rib 15	2	57-834-01	57-834-01	57-834-01	-	-	-
						57-838-01	57-838-01	57-838-01	-	-	-
						57-926-02	57-926-02	57-926-02	-	-	-
						57-930-02	57-930-02	57-930-02	-	-	-
57-20-I02	Upper Panel	57-20-I02J	Wing Outboard, Upper Panel, Typical Splice Stringer	Upper Panel Splice Stringers @ U-10, U24 from Rib 3 to Rib 15	2	-	-	-	May 2028	May 2028	-
						-	-	-	May 2028	May 2028	-
57-20-I03A	Rear Spar	57-20-I03A	Wing Outboard, Rear Spar Web at FWD Trunnion Fitting	All Fastener locations C/T Rear Spar Chords and FWD Trunnion SPRT Fitting btwn Ribs 7 and 8	1	57-743-01	57-743-01	-	-	-	-
57-20-I03A	Rear Spar	57-20-I03A	Wing Outboard, Rear Spar Web at FWD Trunnion Fitting	All Fastener locations C/T Rear Spar Chords and FWD Trunnion SPRT Fitting btwn Ribs 7 and 8	1	-	-	57-743-03	-	-	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-20-I03A	Rear Spar	57-20-I03A	Wing Outboard, Rear Spar Web at FWD Trunnion Fitting	All Fastener locations C/T Rear Spar Chords and FWD Trunnion SPRT Fitting btwn Ribs 7 and 8	FLS1	-	-	-	January 2022	January 2022	-
57-20-I03A	Rear Spar	57-20-I03A	Wing Outboard, Rear Spar Web at FWD Trunnion Fitting	All Fastener locations C/T Rear Spar Chords and FWD Trunnion SPRT Fitting btwn Ribs 7 and 8	FLS1	-	-	-	January 2022	January 2022	-
57-20-I03A	Rear Spar	57-20-I03A	Rear Spar Web at Fwd Trunnion Support Fitting attachment	Fasteners at the Lower Rear Spar Chord and the Upper Rear Spar Chord common to the Rear Spar Web between Ribs 7 and 8	FLS1	-	-	-	-	-	May 2023
57-20-I03A	Rear Spar	57-20-I03A	Rear Spar Web at Fwd Trunnion Support Fitting attachment	Fasteners at the Lower Rear Spar Chord and the Upper Rear Spar Chord common to the Rear Spar Web between Ribs 7 and 8	FLS1	-	-	-	-	-	May 2023
57-20-I04	Front Spar	57-20-I04A	Outboard Wing - Front Spar Splice between Ribs 43 and 44	Front Spar Splice between Ribs 43 and 44	FLS1	-	-	-	January 2022	January 2022	May 2023
		57-20-I04A	Outboard Wing - Front Spar Splice between Ribs 43 and 44	Front Spar Splice between Ribs 43 and 44	FLS1	-	-	-	January 2022	January 2022	May 2023



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-20-I06	Shear Tied Ribs	57-20-I06A	Wing Box Flap Support FTG, Shear Tie Ribs	All Fastener locations C/T Flap Support Back-up Fittings and Shear Tie Ribs 12, 21, 30	2	-	-	-	May 2028	May 2028	-
57-20-I06	Shear Tied Ribs	57-20-I06A	Wing Box Flap Support Fitting at Shear Tie Rib #30	Fastener locations common to the Flap Support Back-up Fittings and Shear Tied Ribs	FLS2	-	-	-	-	-	May 2028
57-20-I06	Shear Tied Ribs	57-20-I06A	Wing Box Flap Support Fitting at Shear Tie Rib #30	Fastener locations common to the Flap Support Back-up Fittings and Shear Tied Ribs	FLS2	-	-	-	-	-	May 2028
57-20-I11	Ribs Number 2 and 9 - Internal Fittings and Adjacent Webs	57-20-I11	Back-up Fitting Typical Rib #9 (P/N 112W5093)	Wing Station 414.5	2	-	-	-	-	-	September 2025
57-30-I01	Lower Panel	57-30-I01A	Lower Panel- Wing Tip Splice at Rib 50	Tension Bolts at Rear Spar	1	-	-	-	January 2025	January 2025	September 2028
57-30-I01	Lower Panel	57-30-I01B	Lower Panel- Wing Tip Splice at Rib 50	Tension Bolts at Front Spar	1	-	-	-	January 2025	January 2025	September 2028
57-30-I01	Lower Panel	57-30-I01C	Lower Panel- Wing Tip Splice at Rib 50	Fitting Pad at Front Spar	1	-	-	-	January 2025	January 2025	September 2028
57-30-I01	Lower Panel	57-30-I01D	Lower Panel- Wing Tip Splice at Rib 50	Lower Skin Attachment at Rear Spar	2	-	-	-	May 2028	May 2028	September 2035
					2	-	-	-	May 2028	May 2022	September 2035
57-53-I07	Inboard Main Flap Outboard Support	57-53-I07A	Inboard Main Flap Outboard Closeout Rib	Aft Access Hole	2	57-751-01	-	57-751-01	-	-	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-53-I07	Inboard Main Flap Outboard Support	57-53-I07A	Inboard Main Flap Outboard Closeout Rib	Aft Access Hole	2	-	57-751-01	-	-	-	-
57-53-I07	Inboard Main Flap Outboard Support	57-53-I07A	Inboard Main Flap Outboard Closeout Rib	Aft Access Hole	2	-	-	-	May 2028	May 2028	-
57-53-I07	Inboard Main Flap Outboard Support	57-53-I07A	Inboard Main Flap Outboard Closeout Rib	Aft Access Hole	2	-	-	-	-	-	September 2035
57-53-I07	Inboard Main Flap Outboard Support	57-53-I07B	Inboard Main Flap Outboard Ribs	Aft Carrier Beam Attachments	2	57-752-01	57-752-01	57-752-01	-	-	-
57-53-I07	Inboard Main Flap Outboard Support	57-53-I07B	Inboard Main Flap Outboard Ribs	Aft Carrier Beam Attachments	2	-	-	-	-	-	September 2035
57-53-I10	Inboard Main Flap Torque Tube	57-53-I10	Inboard Main Flap Torque Tube	Cross-section just Outboard of Closeout Rib Splines	1	57-753-01	57-753-01	57-753-01	January 2025	January 2025	-
57-53-I10	Inboard Main Flap Torque Tube	57-53-I10	Inboard Main Flap Torque Tube	Cross-section just Outboard of Closeout Rib Splines	1	-	-	-	-	-	September 2028
57-53-I11	Inboard Main Flap Inboard Closeout Rib	57-53-I11A	Inboard Main Flap Inboard Closeout Rib	Section thru Lower Chord at Forward Track Support	1	57-754-01	-	-	-	-	-
57-53-I11	Inboard Main Flap Inboard Closeout Rib	57-53-I11A	Inboard Main Flap Inboard Closeout Rib	Section thru Lower Chord at Forward Track Support	1	-	57-754-01	-	-	-	-
57-53-I11	Inboard Main Flap Inboard Closeout Rib	57-53-I11A	Inboard Main Flap Inboard Closeout Rib	Section thru Lower Chord at Forward Track Support	1	-	-	57-754-01	-	-	-
57-53-I11	Inboard Main Flap Inboard Closeout Rib	57-53-I11A	Inboard Main Flap Inboard Closeout Rib	Section thru Lower Chord at Forward Track Support	1	-	-	-	January 2025	January 2025	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-53-I11	Inboard Main Flap Inboard Closeout Rib	57-53-I11A	Inboard Main Flap Inboard Closeout Rib	Section thru Lower Chord at Forward Track Support	1	-	-	-	-	-	September 2028
57-53-I11	Inboard Main Flap Inboard Closeout Rib	57-53-I11B	Inboard Main Flap Inboard Closeout Rib	Section through Torque Tube Access Hole	1	57-755-01	-	-	-	-	-
57-53-I11	Inboard Main Flap Inboard Closeout Rib	57-53-I11B	Inboard Main Flap Inboard Closeout Rib	Section through Torque Tube Access Hole	1	-	57-755-03	-	-	-	-
57-53-I11	Inboard Main Flap Inboard Closeout Rib	57-53-I11B	Inboard Main Flap Inboard Closeout Rib	Section through Torque Tube Access Hole	1	-	-	57-755-01	-	-	-
						-	-	57-755-04	-	-	-
57-53-I11	Inboard Main Flap Inboard Closeout Rib	57-53-I11B	Inboard Main Flap Inboard Closeout Rib	Section through Torque Tube Access Hole	1	-	-	-	January 2025	January 2025	-
57-53-I11	Inboard Main Flap Inboard Closeout Rib	57-53-I11B	Inboard Main Flap Inboard Closeout Rib	Section through Torque Tube Access Hole	1	-	-	-	-	-	September 2028
57-53-I11	Inboard Main Flap Inboard Closeout Rib	57-53-I11C	Inboard Main Flap Inboard Closeout Rib	Spline Region	1	57-756-01	57-756-01	57-756-01	January 2025	January 2025	-
57-53-I11	Inboard Main Flap Inboard Closeout Rib	57-53-I11C	Inboard Main Flap Inboard Closeout Rib	Spline Region	1	-	-	-	-	-	September 2028
57-53-I16	Inboard Flap - No. 3 Support Underwing Attach Fitting	57-53-I16A	No. 3 (and No. 6) Inboard Flap Support Underwing Fitting	Lugs, Outer Lug	1	57-757-01	-	-	-	-	-
57-53-I16	Inboard Flap - No. 3 Support Underwing Attach Fitting	57-53-I16A	No. 3 (and No. 6) Inboard Flap Support Underwing Fitting	Lugs, Outer Lug	1	-	57-757-01	-	-	-	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-53-I16	Inboard Flap - No. 3 Support Underwing Attach Fitting	57-53-I16A	No. 3 (and No. 6) Inboard Flap Support Underwing Fitting	Lugs, Outer Lug	1	-	-	57-757-01	-	-	-
57-53-I16	Inboard Flap - No. 3 Support Underwing Attach Fitting	57-53-I16A	No. 3 (and No. 6) Inboard Flap Support Underwing Fitting	Lugs, Outer Lug	1	-	-	-	January 2025	January 2025	September 2028
57-53-I16	Inboard Flap - No. 3 Support Underwing Attach Fitting	57-53-I16B	No. 3 (and No. 6) Inboard Flap Support Underwing Fitting	Lugs, Inner Lug	1	57-758-01	-	-	-	-	-
57-53-I16	Inboard Flap - No. 3 Support Underwing Attach Fitting	57-53-I16B	No. 3 (and No. 6) Inboard Flap Support Underwing Fitting	Lugs, Inner Lug	1	-	57-758-01	-	-	-	-
57-53-I16	Inboard Flap - No. 3 Support Underwing Attach Fitting	57-53-I16B	No. 3 (and No. 6) Inboard Flap Support Underwing Fitting	Lugs, Inner Lug	1	-	-	57-758-01	-	-	-
57-53-I16	Inboard Flap - No. 3 Support Underwing Attach Fitting	57-53-I16C	No. 3 (and No. 6) Inboard Flap Support Underwing Fitting	Section at Aft Main Attach Bolt (Section C-C)	1	57-759-01	-	-	-	-	-
57-53-I16	Inboard Flap - No. 3 Support Underwing Attach Fitting	57-53-I16C	No. 3 (and No. 6) Inboard Flap Support Underwing Fitting	Section at Aft Main Attach Bolt (Section C-C)	1	-	57-759-01	-	-	-	-
57-53-I16	Inboard Flap - No. 3 Support Underwing Attach Fitting	57-53-I16C	No. 3 (and No. 6) Inboard Flap Support Underwing Fitting	Section at Aft Main Attach Bolt (Section C-C)	1	-	-	57-759-01	-	-	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-53-I16	Inboard Flap - No. 3 Support Underwing Attach Fitting	57-53-I16C	No. 3 (and No. 6) Inboard Flap Support Underwing Fitting	Section at Aft Main Attach Bolt (Section C-C)	1	-	-	-	January 2025	January 2025	September 2028
57-53-I18	Inboard Flap - No. 3 Support Forward Tension Link	57-53-I18A	No. 3 (and No. 6) Inboard Flap Support Forward Tension Link	Aft Clevis Fillet, Inboard Lug	1	57-760-01	-	-	-	-	-
						57-760-03	-	-	-	-	-
57-53-I18	Inboard Flap - No. 3 Support Forward Tension Link	57-53-I18A	No. 3 (and No. 6) Inboard Flap Support Forward Tension Link	Aft Clevis Fillet, Inboard Lug	1	-	57-760-01	-	-	-	-
						-	57-760-03	-	-	-	-
57-53-I18	Inboard Flap - No. 3 Support Forward Tension Link	57-53-I18B	No. 3 (and No. 6) Inboard Flap Support Forward Tension Link	Center Section	2	57-761-01	-	-	-	-	-
57-53-I18	Inboard Flap - No. 3 Support Forward Tension Link	57-53-I18B	No. 3 (and No. 6) Inboard Flap Support Forward Tension Link	Center Section	2	-	57-761-03	-	-	-	-
						-	57-761-04	-	-	-	-
57-53-I18	Inboard Flap - No. 3 Support Forward Tension Link	57-53-I18B	No. 3 (and No. 6) Inboard Flap Support Forward Tension Link	Center Section	2	-	-	57-761-03	-	-	-
57-53-I18	Inboard Flap - No. 3 Support Forward Tension Link	57-53-I18B	No. 3 (and No. 6) Inboard Flap Support Forward Tension Link	Center Section	2	-	-	-	May 2028	May 2028	September 2035
57-53-I18	Inboard Flap - No. 3 Support Forward Tension Link	57-53-I18C	No. 3 (and No. 6) Inboard Flap Support Forward Tension Link	Lugs	2	57-762-01	-	-	-	-	-
57-53-I18	Inboard Flap - No. 3 Support Forward Tension Link	57-53-I18C	No. 3 (and No. 6) Inboard Flap Support Forward Tension Link	Lugs	2	-	57-762-01	-	-	-	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-53-I18	Inboard Flap - No. 3 Support Forward Tension Link	57-53-I18C	No. 3 (and No. 6) Inboard Flap Support Forward Tension Link	Lugs	2	-	-	57-762-01	-	-	-
57-53-I18	Inboard Flap - No. 3 Support Forward Tension Link	57-53-I18C	No. 3 (and No. 6) Inboard Flap Support Forward Tension Link	Lugs	2	-	-	-	May 2028	May 2028	September 2035
57-53-I20	Inboard Flap - No. 3 Support Aft Tension Beam	57-53-I20A	No. 3 (and No. 6) Inboard Flap Support Aft Tension Beam	Forward and Aft Lugs	2	57-763-01	-	-	-	-	-
57-53-I20	Inboard Flap - No. 3 Support Aft Tension Beam	57-53-I20A	No. 3 (and No. 6) Inboard Flap Support Aft Tension Beam	Forward and Aft Lugs	2	-	57-763-01	-	-	-	-
57-53-I20	Inboard Flap - No. 3 Support Aft Tension Beam	57-53-I20A	No. 3 (and No. 6) Inboard Flap Support Aft Tension Beam	Forward and Aft Lugs	2	-	-	57-763-01	-	-	-
57-53-I20	Inboard Flap - No. 3 Support Aft Tension Beam	57-53-I20A	No. 3 (and No. 6) Inboard Flap Support Aft Tension Beam	Forward and Aft Lugs	2	-	-	-	May 2028	May 2028	-
57-53-I20	Inboard Flap - No. 3 Support Aft Tension Beam	57-53-I20A	No. 3 (and No. 6) Inboard Flap Support Aft Tension Beam	Aft Lug - Pin D (Forward and Aft Lugs)	2	-	-	-	-	-	September 2035
57-53-I20	Inboard Flap - No. 3 Support Aft Tension Beam	57-53-I20B	No. 3 (and No. 6) Inboard Flap Support Aft Tension Beam	General Section	2	57-764-01	-	-	-	-	-
57-53-I20	Inboard Flap - No. 3 Support Aft Tension Beam	57-53-I20B	No. 3 (and No. 6) Inboard Flap Support Aft Tension Beam	General Section	2	-	57-764-01	-	-	-	-
57-53-I20	Inboard Flap - No. 3 Support Aft Tension Beam	57-53-I20B	No. 3 (and No. 6) Inboard Flap Support Aft Tension Beam	General Section	2	-	-	57-764-01	-	-	-
						-	-	57-764-03	-	-	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-53-I20	Inboard Flap - No. 3 Support Aft Tension Beam	57-53-I20B,C	No. 3 (and No. 6) Inboard Flap Support Aft Tension Beam	General Section (includes area around compression rod attachment point)	2	-	-	-	May 2028	May 2028	-
57-53-I20	Inboard Flap - No. 3 Support Aft Tension Beam	57-53-I20C	No. 3 (and No. 6) Inboard Flap Support Aft Tension Beam	Aft Section of Beam, area around compression rod attachment point	2	57-765-01	-	-	-	-	-
						57-765-03	-	-	-	-	-
57-53-I20	Inboard Flap - No. 3 Support Aft Tension Beam	57-53-I20C	No. 3 (and No. 6) Inboard Flap Support Aft Tension Beam	Aft Section of Beam, area around compression rod attachment point	2	-	57-765-01	-	-	-	-
						-	57-765-04	-	-	-	-
57-53-I20	Inboard Flap - No. 3 Support Aft Tension Beam	57-53-I20C	No. 3 (and No. 6) Inboard Flap Support Aft Tension Beam	Aft Section of Beam, area around compression rod attachment point	2	-	-	57-765-01	-	-	-
						-	-	57-765-04	-	-	-
57-53-I20	Inboard Flap - No. 3 Support Aft Tension Beam	57-53-I20C	No. 3 (and No. 6) Inboard Flap Support Aft Tension Beam	Aft Section of Beam	2	-	-	-	-	-	September 2035
57-53-I21	Inboard Flap - No. 3 Support Pivot Link	57-53-I21A	No. 3 (and No. 6) Inboard Flap Support Pivot Link	Lug Cross-Sections	2	57-766-01	-	-	-	-	-
57-53-I21	Inboard Flap - No. 3 Support Pivot Link	57-53-I21A	No. 3 (and No. 6) Inboard Flap Support Pivot Link	Lug Cross-Sections	2	-	57-766-01	-	-	-	-
57-53-I21	Inboard Flap - No. 3 Support Pivot Link	57-53-I21A	No. 3 (and No. 6) Inboard Flap Support Pivot Link	Lug Cross-Sections	2	-	-	57-766-01	-	-	-
57-53-I21	Inboard Flap - No. 3 Support Pivot Link	57-53-I21A	No. 3 (and No. 6) Inboard Flap Support Pivot Link	Lug Cross-Sections	2	-	-	-	May 2028	May 2028	September 2035



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-53-I21	Inboard Flap - No. 3 Support Pivot Link	57-53-I21B	No. 3 (and No. 6) Inboard Flap Support Pivot Link	Center Section thru Fastener	1	57-767-01	-	-	-	-	-
57-53-I21	Inboard Flap - No. 3 Support Pivot Link	57-53-I21B	No. 3 (and No. 6) Inboard Flap Support Pivot Link	Center Section thru Fastener	1	-	57-767-01	-	-	-	-
57-53-I21	Inboard Flap - No. 3 Support Pivot Link	57-53-I21B	No. 3 (and No. 6) Inboard Flap Support Pivot Link	Center Section thru Fastener	1	-	-	57-767-01	-	-	-
57-53-I21	Inboard Flap - No. 3 Support Pivot Link	57-53-I21B	No. 3 (and No. 6) Inboard Flap Support Pivot Link	Center Section thru Fastener	1	-	-	-	January 2025	January 2025	September 2028
57-53-I23	Inboard Flap - No. 3 Support Drive Arm	57-53-I23	No. 3 (and No. 6) Inboard Flap Support Drive Arm Assembly	3rd Fastener Row from Forward Inboard Side	1	57-768-01	-	-	-	-	-
57-53-I23	Inboard Flap - No. 3 Support Drive Arm	57-53-I23	No. 3 (and No. 6) Inboard Flap Support Drive Arm Assembly	3rd Fastener Row from Forward Inboard Side	1	-	57-768-01	-	-	-	-
						-	57-768-03	-	-	-	-
57-53-I24	Inboard Flap - No. 3 Support Carrier Beam	57-53-I24A	No. 3 (and No. 6) Inboard Flap Support Carrier Beam	Inboard Forward Arm	2	57-769-01	-	-	-	-	-
						57-769-03	-	-	-	-	-
57-53-I24	Inboard Flap - No. 3 Support Carrier Beam	57-53-I24A	No. 3 (and No. 6) Inboard Flap Support Carrier Beam	Inboard Forward Arm	2	-	57-769-01	-	-	-	-
						-	57-769-03	-	-	-	-
57-53-I24	Inboard Flap - No. 3 Support Carrier Beam	57-53-I24A	No. 3 (and No. 6) Inboard Flap Support Carrier Beam	Inboard Forward Arm	2	-	-	57-769-01	-	-	-
						-	-	57-769-03	-	-	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-53-I24	Inboard Flap - No. 3 Support Carrier Beam	57-53-I24A	No. 3 (and No. 6) Inboard Flap Support Carrier Beam	Inboard Forward Arm	2	-	-	-	May 2028	May 2028	September 2035
57-53-I24	Inboard Flap - No. 3 Support Carrier Beam	57-53-I24B	No. 3 (and No. 6) Inboard Flap Support Carrier Beam	Cross-Over Beam	1	57-771-01	-	-	-	-	-
57-53-I24	Inboard Flap - No. 3 Support Carrier Beam	57-53-I24B	No. 3 (and No. 6) Inboard Flap Support Carrier Beam	Cross-Over Beam	1	-	57-771-01	-	-	-	-
						-	57-771-03	-	-	-	-
57-53-I24	Inboard Flap - No. 3 Support Carrier Beam	57-53-I24B	No. 3 (and No. 6) Inboard Flap Support Carrier Beam	Cross-Over Beam	1	-	-	57-771-01	-	-	-
57-53-I24	Inboard Flap - No. 3 Support Carrier Beam	57-53-I24C	No. 3 (and No. 6) Inboard Flap Support Carrier Beam	Flap Forward Attachment	1	57-772-01	-	-	-	-	-
57-53-I24	Inboard Flap - No. 3 Support Carrier Beam	57-53-I24C	No. 3 (and No. 6) Inboard Flap Support Carrier Beam	Flap Forward Attachment	1	-	57-772-01	-	-	-	-
57-53-I24	Inboard Flap - No. 3 Support Carrier Beam	57-53-I24C	No. 3 (and No. 6) Inboard Flap Support Carrier Beam	Flap Forward Attachment	1	-	-	57-772-01	-	-	-
57-53-I24	Inboard Flap - No. 3 Support Carrier Beam	57-53-I24C	No. 3 (and No. 6) Inboard Flap Support Carrier Beam	Flap Forward Attachment	1	-	-	-	January 2025	January 2025	-
57-53-I24	Inboard Flap - No. 3 Support Carrier Beam	57-53-I24D	No. 3 (and No. 6) Inboard Flap Support Carrier Beam	Flap Aft Attachment	1	57-773-01	-	-	-	-	-
57-53-I24	Inboard Flap - No. 3 Support Carrier Beam	57-53-I24D	No. 3 (and No. 6) Inboard Flap Support Carrier Beam	Flap Aft Attachment	1	-	57-773-01	-	-	-	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-53-I24	Inboard Flap - No. 3 Support Carrier Beam	57-53-I24D	No. 3 (and No. 6) Inboard Flap Support Carrier Beam	Flap Aft Attachment	1	-	-	57-773-01	-	-	-
57-53-I24	Inboard Flap - No. 3 Support Carrier Beam	57-53-I24D	No. 3 (and No. 6) Inboard Flap Support Carrier Beam	Flap Aft Attachment	1	-	-	-	January 2025	January 2025	-
57-53-I24	Inboard Flap - No. 3 Support Carrier Beam	57-53-I24F	No. 3 (and No. 6) Inboard Flap Support Carrier Beam	'B' Point Lug	1	57-774-01	57-774-01	57-774-01	-	-	-
57-53-I24	Inboard Flap - No. 3 Support Carrier Beam	57-53-I24G	No. 3 (and No. 6) Inboard Flap Support Carrier Beam	'C' Point Lug	1	57-775-01	57-775-01	-	-	-	-
57-53-I24	Inboard Flap - No. 3 Support Carrier Beam	57-53-I24G	No. 3 (and No. 6) Inboard Flap Support Carrier Beam	'C' Point Lug	1	-	-	57-775-01	-	-	-
57-53-I24	Inboard Flap - No. 3 Support Carrier Beam	57-53-I24G	No. 3 (and No. 6) Inboard Flap Support Carrier Beam	'C' Point Lug	1	-	-	-	January 2025	January 2025	-
57-53-I24	Inboard Flap - No. 3 Support Carrier Beam	57-53-I24G	No. 3 (and No. 6) Inboard Flap Support Carrier Beam	'C' Point Lug	1	-	-	-	-	-	September 2028
57-53-I26	Inboard Flap - No. 3 Support Pins	57-53-I26A	No. 3 (and No. 6) Inboard Flap Support 113W1027	Outer Pins A, B, and W	1	57-776-01	57-776-01	57-776-01	January 2025	January 2025	September 2028
57-53-I26	Inboard Flap - No. 3 Support Pins	57-53-I26B	No. 3 (and No. 6) Inboard Flap Support 113W1027	Outer Pins C, D, X, and Y	1	57-777-01	57-777-01	57-777-01	January 2025	January 2025	September 2028
57-53-I27	Inboard Flap - No. 4 Support Drive Arm	57-53-I27A	No. 4 (and No. 5) Inboard Flap Support Drive Arm	Joint 'A' Pivot Hole	2	57-778-01	-	-	-	-	-
57-53-I27	Inboard Flap - No. 4 Support Drive Arm	57-53-I27A	No. 4 (and No. 5) Inboard Flap Support Drive Arm	Joint 'A' Pivot Hole	2	-	57-778-01	-	-	-	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-53-I27	Inboard Flap - No. 4 Support Drive Arm	57-53-I27A	No. 4 (and No. 5) Inboard Flap Support Drive Arm	Joint 'A' Pivot Hole	2	-	-	57-778-01	-	-	-
57-53-I27	Inboard Flap - No. 4 Support Drive Arm	57-53-I27A	No. 4 (and No. 5) Inboard Flap Support Drive Arm	Joint 'A' Pivot Hole	2	-	-	-	May 2028	May 2028	September 2035
57-53-I27	Inboard Flap - No. 4 Support Drive Arm	57-53-I27B	No. 4 (and No. 5) Inboard Flap Support Drive Arm	'B' Point Lugs	2	57-779-01	-	57-779-01	-	-	-
57-53-I27	Inboard Flap - No. 4 Support Drive Arm	57-53-I27B	No. 4 (and No. 5) Inboard Flap Support Drive Arm	'B' Point Lugs	2	-	57-779-01	-	-	-	-
57-53-I27	Inboard Flap - No. 4 Support Drive Arm	57-53-I27B	No. 4 (and No. 5) Inboard Flap Support Drive Arm	'B' Point Lugs	2	-	-	-	May 2028	May 2028	September 2035
57-53-I28	Inboard Flap - No. 4 Support Actuator Support	57-53-I28A	No. 4 (and No. 5) Inboard Flap Support Actuator Support Fitting	Outboard Beam at 9.88 inches Aft of Point 'A'	2	57-780-01	-	-	-	-	-
57-53-I28	Inboard Flap - No. 4 Support Actuator Support	57-53-I28A	No. 4 (and No. 5) Inboard Flap Support Actuator Support Fitting	Outboard Beam at 9.88 inches Aft of Point 'A'	2	-	57-780-01	-	-	-	-
57-53-I28	Inboard Flap - No. 4 Support Actuator Support	57-53-I28A	No. 4 (and No. 5) Inboard Flap Support Actuator Support Fitting	Outboard Beam at 9.88 inches Aft of Point 'A'	2	-	-	57-780-01	-	-	-
57-53-I28	Inboard Flap - No. 4 Support Actuator Support	57-53-I28A	No. 4 (and No. 5) Inboard Flap Support Actuator Support Fitting	Outboard Beam at 9.88 inches Aft of Point 'A'	2	-	-	-	May 2028	May 2028	September 2035
57-53-I28	Inboard Flap - No. 4 Support Actuator Support	57-53-I28B	No. 4 (and No. 5) Inboard Flap Support Actuator Support Fitting	Point 'A' Lugs	2	57-781-01	-	57-781-01	-	-	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-53-I28	Inboard Flap - No. 4 Support Actuator Suppor	57-53-I28B	No. 4 (and No. 5) Inboard Flap Support Actuator Support Fitting	Point 'A' Lugs	2	-	57-781-01	-	-	-	-
57-53-I28	Inboard Flap - No. 4 Support Actuator Suppor	57-53-I28B	No. 4 (and No. 5) Inboard Flap Support Actuator Support Fitting	Point 'A' Lugs	2	-	-	-	May 2028	May 2028	September 2035
57-53-I29	Inboard Flap - No. 4 Support Carrier Beam	57-53-I29A	No. 4 (and No. 5) Inboard Flap Support Carrier Beam	Section at Torque Tube Attachment Fitting	1	57-782-01	-	-	-	-	-
57-53-I29	Inboard Flap - No. 4 Support Carrier Beam	57-53-I29A	No. 4 (and No. 5) Inboard Flap Support Carrier Beam	Section at Torque Tube Attachment Fitting	1	-	57-782-01	-	-	-	-
57-53-I29	Inboard Flap - No. 4 Support Carrier Beam	57-53-I29A	No. 4 (and No. 5) Inboard Flap Support Carrier Beam	Section at Torque Tube Attachment Fitting	1	-	-	57-782-01	-	-	-
57-53-I29	Inboard Flap - No. 4 Support Carrier Beam	57-53-I29A	No. 4 (and No. 5) Inboard Flap Support Carrier Beam	Section at Torque Tube Attachment Fitting	1	-	-	-	January 2025	January 2025	September 2028
57-53-I29	Inboard Flap - No. 4 Support Carrier Beam	57-53-I29B	No. 4 (and No. 5) Inboard Flap Support Pillow Block	Section at Aft Fasteners	1	57-783-01	-	-	-	-	-
57-53-I29	Inboard Flap - No. 4 Support Carrier Beam	57-53-I29B	No. 4 (and No. 5) Inboard Flap Support Pillow Block	Section at Aft Fasteners	1	-	57-783-01	-	-	-	-
57-53-I29	Inboard Flap - No. 4 Support Carrier Beam	57-53-I29B	No. 4 (and No. 5) Inboard Flap Support Pillow Block	Section at Aft Fasteners	1	-	-	57-783-01	-	-	-
57-53-I29	Inboard Flap - No. 4 Support Carrier Beam	57-53-I29B	No. 4 (and No. 5) Inboard Flap Support Pillow Block	Section at Aft Fasteners	1	-	-	-	January 2025	January 2025	September 2028



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-53-I33	Inboard Flap - No. 4 Support Pins	57-53-I33	No. 4 (and No. 5) Inboard Flap Support Pins	Inner and Outer Pin B	1	57-784-01	57-784-01	57-784-01	January 2025	January 2025	September 2028
57-53-I34	Outboard Flap - Underwing Fitting Dual Bolts	57-53-I34	No. 1 (and No. 8) Outboard Flap Support and No.2 (and No. 7) Outboard Flap Support	Underwing Fitting Inner and Outer Pins	1	57-785-01	57-785-01	57-785-01	January 2025	January 2025	-
57-54-I17	Main Landing Gear Forward Trunnion Support Fitting	57-54-I17A	MLG FWD Trunnion Sideload Fitting	All fastener locations C/T Sideload Fitting and Sideload Straps	2	57-786-01	57-786-01	-	-	-	-
57-54-I17	Main Landing Gear Forward Trunnion Support Fitting	57-54-I17A	MLG FWD Trunnion Sideload Fitting	All fastener locations C/T Sideload Fitting and Sideload Straps	2	-	-	57-786-01	-	-	-
57-54-I17	Main Landing Gear Forward Trunnion Support Fitting	57-54-I17B	MLG FWD Trunnion Sideload Straps	All Fastener Locations C/T Upper/Lower Strap and INBD O/B Vertical Support Fitting	2	57-787-01	57-787-01	-	-	-	-
57-54-I17	Main Landing Gear Forward Trunnion Support Fitting	57-54-I17B	MLG FWD Trunnion Sideload Straps	All Fastener Locations C/T Upper/Lower Strap and INBD O/B Vertical Support Fitting	2	-	-	57-787-01	-	-	-
57-54-I17	Main Landing Gear Forward Trunnion Support Fitting	57-54-I17C	MLG FWD Trunnion Outboard Support Fitting, R/S Attach Fitting Flange	All Fasteners Locations C/T 112W1702 and 112W1704 FTG and R/Spar Web	2	57-788-01	-	-	-	-	-
					FLS2	-	57-788-02	-	-	-	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-54-I17	Main Landing Gear Forward Trunnion Support Fitting	57-54-I17C	MLG FWD Trunnion Outboard Support Fitting, R/S Attach Fitting Flange	All Fasteners Locations C/T 112W1702 and 112W1704 FTG and R/Spar Web	FLS2	-	57-788-03	-	-	-	-
						-	57-788-04	-	-	-	-
					2	-	-	57-788-01	-	-	-
						-	-	57-788-05	-	-	-
57-54-I17	Main Landing Gear Forward Trunnion Support Fitting	57-54-I17C	MLG FWD Trunnion Outboard Support Fitting, R/S Attach Fitting Flange	All Fasteners Locations C/T 112W1702 and 112W1704 FTG and R/Spar Web	FLS2	-	-	-	January 2025	January 2025	-
57-54-I17	Main Landing Gear Forward Trunnion Support Fitting	57-54-I17C	MLG FWD Trunnion Outboard Support Fitting, R/S Attach Fitting Flange	All Fasteners Locations C/T 112W1702 and 112W1704 FTG and R/Spar Web	FLS2	-	-	-	January 2025	January 2025	-
57-54-I17	Main Landing Gear Forward Trunnion Support Fitting	57-54-I17C	112W1704, MLG FWD Trunnion Support Fitting	Section A-A, Spar Flange Crack	FLS2	-	-	-	-	-	May 2028
57-54-I17	Main Landing Gear Forward Trunnion Support Fitting	57-54-I17C	112W1704, MLG FWD Trunnion Support Fitting	Section A-A, Spar Flange Crack	FLS2	-	-	-	-	-	May 2028
57-54-I18	Main Landing Gear Beam Outboard Support Fitting	57-54-I18A	MLG Beam OBD Support FTG, Lwr Skin Flange	All fastener holes locations C/T Lower flange and Lower Skin Panel	2	57-790-01	57-790-01	-	-	-	-
57-54-I18	Main Landing Gear Beam Outboard Support Fitting	57-54-I18A	MLG Beam OBD Support FTG, Lwr Skin Flange	All fastener holes locations C/T Lower flange and Lower Skin Panel	2	-	-	57-790-02	-	-	-
						-	-	57-790-03	-	-	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-54-I18	Main Landing Gear Beam Outboard Support Fitting	57-54-I18B	MLG Beam OBD Support FTG, Fitting	Lower Horizontal Rib of MLG Beam Support Fitting @ Fastener Hole	2	-	-	-	May 2028	May 2028	-
57-54-I18	Main Landing Gear Beam Outboard Support Fitting	57-54-I18B	112W1722, MLG Beam Outboard Support Fitting	Lower Horizontal Rib, Section A-A Lead crack at fastener hole	FLS2	-	-	-	-	-	May 2028
57-54-I18	Main Landing Gear Beam Outboard Support Fitting	57-54-I18B	112W1722, MLG Beam Outboard Support Fitting	Lower Horizontal Rib, Section A-A Lead crack at fastener hole	FLS2	-	-	-	-	-	May 2028
57-54-I18	Main Landing Gear Beam Outboard Support Fitting	57-54-I18C	MLG Beam OBD Support FTG, Fitting	Lower Horizontal Rib of MLG Beam Support Fitting @ Free Edge	2	-	-	-	May 2028	May 2028	-
57-54-I18	Main Landing Gear Beam Outboard Support Fitting	57-54-I18C	112W1722, MLG Beam Outboard Support Fitting	Lower Horizontal Rib, Section A-A Lead Crack at Free Edge	FLS2	-	-	-	-	-	May 2028
57-54-I18	Main Landing Gear Beam Outboard Support Fitting	57-54-I18C	112W1722, MLG Beam Outboard Support Fitting	Lower Horizontal Rib, Section A-A Lead Crack at Free Edge	FLS2	-	-	-	-	-	May 2028
57-54-I19	Main Landing Gear Drag Brace Support Fitting	57-54-I19A	MLG Drag Brace Support Fitting	Section A-A Flange Crack	2	57-793-01	57-793-01	-	-	-	-
57-54-I19	Main Landing Gear Drag Brace Support Fitting	57-54-I19A	MLG Drag Brace Support Fitting	Section A-A Flange Crack	2	-	-	57-793-02	-	-	-
57-54-I19	Main Landing Gear Drag Brace Support Fitting	57-54-I19A	MLG Drag Brace Support Fitting	Section A-A Flange Crack	2	-	-	-	May 2028	May 2028	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-54-I19	Main Landing Gear Drag Brace Support Fitting	57-54-I19A	112W1752, MLG Drag Brace Support Fitting	Section A-A Flange Crack	FLS2	-	-	-	-	-	May 2028
57-54-I19	Main Landing Gear Drag Brace Support Fitting	57-54-I19A	112W1752, MLG Drag Brace Support Fitting	Section A-A Flange Crack	FLS2	-	-	-	-	-	May 2028
57-54-I19	Main Landing Gear Drag Brace Support Fitting	57-54-I19B	MLG Drag Brace Support Fitting, Base of Fitting	Section A-A Fastener Locations C/T Base of fitting and Rear Spar Web	2	57-794-01	57-794-01	57-794-01	-	-	-
57-54-I19	Main Landing Gear Drag Brace Support Fitting	57-54-I19B	MLG Drag Brace Support Fitting, Base of Fitting	Section A-A Fastener Locations C/T Base of fitting and Rear Spar Web	2	-	-	-	May 2028	May 2028	-
57-54-I19	Main Landing Gear Drag Brace Support Fitting	57-54-I19B	112W1752, MLG Drag Brace Support Fitting	Section A-A Base Crack	FLS2	-	-	-	-	-	May 2028
57-54-I19	Main Landing Gear Drag Brace Support Fitting	57-54-I19B	112W1752, MLG Drag Brace Support Fitting	Section A-A Base Crack	FLS2	-	-	-	-	-	May 2028
57-54-I19	Main Landing Gear Drag Brace Support Fitting	57-54-I19C	MLG Drag Brace Internal Backup Fitting	Entire Fitting C/T SOB Rib and Rear Spar, including Stiffening Ribs	2	-	-	57-795-01	-	-	-
57-54-I19	Main Landing Gear Drag Brace Support Fitting	57-54-I19C	MLG Drag Brace Internal Backup Fitting	Entire Fitting C/T SOB Rib and Rear Spar, including Stiffening Ribs	FLS2	-	-	-	January 2025	January 2025	-
57-54-I19	Main Landing Gear Drag Brace Support Fitting	57-54-I19C	MLG Drag Brace Internal Backup Fitting	Entire fitting c/t SOB Rib and Rear Spar, including Stiffening Ribs	FLS2	-	-	-	January 2025	January 2025	-



777-200/300 MAINTENANCE PLANNING DOCUMENT

Structural Significant Item (SSI)	SSI Title	Suppl. Structural Inspection	DTR Check Form Title	DTR Location	Group	MPD Fatigue Inspection Task					
						-200	-200IGW	-300	-300ER	-200LR	-2020F
57-54-I19	Main Landing Gear Drag Brace Support Fitting	57-54-I19C	112W1756, MLG Drag Brace Support Back-up Fitting	Section A-A, Lead Crack in Base	FLS2	-	-	-	-	-	May 2028
57-54-I19	Main Landing Gear Drag Brace Support Fitting	57-54-I19C	112W1756, MLG Drag Brace Support Back-up Fitting	Section A-A, Lead Crack in Base	FLS2	-	-	-	-	-	May 2028
57-54-I20	Main Landing Gear Retraction Actuator Support Fitting and Pin	57-54-I20	Retraction Actuator Support Fitting, Fitting Attach Flange	Rear Spar Attach Flange	2	57-796-01	57-796-01	57-796-01	-	-	September 2035

